

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)**GENERAL INFORMATION**

(enter either long/lat or UTM below – not both)

*Site #: <u>CLC-2012</u>	*Crossing Name:	*Type/Class: ☒ Temporary bridge ☐ Permanent bridge	*Project File ID# <u>5713</u>
*Structure #:			*Br. <u>02</u>
*FSR Name: <u>Blue Mountain</u>	*Forest District: <u>CLC</u>	*Kilometres:	User km: <u>0.8</u>
Longitude: (ddd / mm / ss.s) <u>49° 14' 09.7"</u>	OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>122° 28' 07.5"</u>			UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G <u>(P)</u> UR	Corners on each side
Bridge Ahead Signs Missing	0 1 <u>(2)</u>	
Brushing Required	Yes <u>No</u>	
Delineator Missing Left	<u>(0)</u> 1 2	
Delineator Missing Right	<u>(0)</u> 1 2	
Fender Condition	E G <u>(P)</u> None UR	Logs
Posted Load Rating	(tonnes) or <u>None</u>	
Road Surface	E <u>(G)</u> F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Crib	E G F P <u>(N/A)</u> UR	
Tie-backs	E G F P <u>(N/A)</u> UR	
Bin Wall	E G F P <u>(N/A)</u> UR	
Concrete (cast in place; lock blocks, precast)	E <u>(G)</u> F P N/A UR	Lock blocks (3 high w/ gravel)
Caps or Sills	E <u>(G)</u> F P N/A UR	Treated timber
Piles or Posts	E G F P <u>(N/A)</u> UR	
Ballast Wall	E <u>(G)</u> F P N/A UR	Treated timber
Wing Wall	E G F P <u>(N/A)</u> UR	
Bracing	E G F P <u>(N/A)</u> UR	
Hardware	E G F P <u>(N/A)</u> UR	
Fill	E <u>(G)</u> F P N/A UR	
Riprap	E G <u>(P)</u> P N/A UR	Right side inadequate
Bearings	E <u>(G)</u> F P N/A UR	
Corrosion Protection	E G F P <u>(N/A)</u> UR	

Span 1 of _____ (spans are numbered consecutively starting from the left abutment)
Use "Additional Spans" Sheet for Multiple Spans**DECK**

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E <u>(G)</u> F P N/A UR	
Running Planks	E G F P <u>(N/A)</u> UR	
Sub-deck	E <u>(G)</u> F P N/A UR	
Ties	E <u>(G)</u> F P N/A UR	
Nails	E <u>(G)</u> F P N/A UR	
Deck to Girder Bolts	E <u>(G)</u> F P N/A UR	
Concrete Deck	E G F P <u>(N/A)</u> UR	
Grout Pockets	E G F P <u>(N/A)</u> UR	
Deck Joints	E G F P <u>(N/A)</u> UR	
Steel Deck Plate	E G F P <u>(N/A)</u> UR	
Gravel Surface	E G F P <u>(N/A)</u> UR	
Gravel Deck Depth	metres or <u>(N/A)</u>	
Curb Rail/Blocks/Posts	E <u>(G)</u> F P UR	
Handrails/Walkouts	E G F P <u>(N/A)</u> UR	
Hardware	E <u>(G)</u> F P N/A UR	
Overall Deck Condition	E <u>(G)</u> F P UR	

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Site #: <u>CL-2017</u>		*Structure #:	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E <u>(G)</u> F P UR	Weathering steel (MBS)	
Diaphragms	E G F P <u>(N/A)</u> UR		
Bracing	E <u>(G)</u> F P N/A UR		
Under-trussing	E G F P <u>(N/A)</u> UR		
Hardware	E <u>(G)</u> F P N/A UR		
Welded / Grouted Shear Connectors	E G F P <u>(N/A)</u> UR		
Stream CHANNEL			
*Est. Present Water Level Depth <u>0.2</u> (m)		*Est. Present Water Level Width <u>3</u> (m)	*Est. High Water Level Clearance <u>3</u> (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes <u>(No)</u>	Scour?	Yes <u>(No)</u>
Ice?	Yes <u>(No)</u>	D debris?	Yes <u>(No)</u>
Aggradation?	Yes <u>(No)</u>		
Comments			
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		
2	H M L		
3	H M L		
*Monitoring Status: ☒ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1	MONITOR RIGHT ABUTMENT FILL @ CRIC		
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	L→R		From left
	U/L		Right about
	D/L		Left view
	R→L		Left bearings
			left about 5 girders
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes <u>(No)</u>		P Eng Inspection Required? Yes <u>(No)</u>	
		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): <u>2030</u> <small>(P Eng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)</small>	
*Date of Inspection (yyyy/mm/dd) <u>2011/11/08</u>	*Inspection Company Name <u>ONSITE ENG LTD</u>	*Inspector's Name (print) <u>J. C. P. ARAKI</u>	Inspector's Signature
Inspector's Comments			
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION			
Current Load Rating GVW (tonnes): <u>68 tonnes</u> <small>(P Eng to update structure details screen in CBR as necessary)</small>		Date of Next Planned Inspection (yyyy/mm/dd) <u>2013/10/31</u>	
Reviewer Company Name <u>MOF</u>	Reviewed by - P Eng's Name (print) <u>T. Miller</u>	Reviewed by - P Eng's Signature 	Date Reviewed (yyyy/mm/dd) <u>Jan. 10, 2012</u>
P Eng Reviewer's Comments			

* Denotes Mandatory Information for Corporate Bridge Register

Post bridge ahead signs. Present load rating of L75 or 68 tonnes to continue.



CK2012 Downstream



CK2012 Left to Right Approach



CK2012 Right to Left Approach



CK2012 Upstream



CK2012 Left Abutment rip rap



CK2012 From Upstream



CK2012 Left Abutment bearing



CK2012 Right Abutment



CK2012 Left Abutment



CK2012 Girders