

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION** (enter either long/lat or UTM below – not both)

*Site #: <u>CL 2267</u>	*Crossing Name: <u>Unknown</u>	*Type/Class: ☐ Major Culvert ☒ Woodbox/Log Culvert	*Project File ID# <u>8013</u>
*Structure #:			*Br. <u>01</u>
*FSR Name: <u>Stave River</u>	*Forest District: <u>CL</u>	*Kilometres: <u>10.5km</u>	User km:
Longitude: (ddd / mm / ss.s) <u>W122° 15' 24.1"</u>	OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>N49° 29' 6.1"</u>			UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G (F) P UR	<u>Tight horizontal</u>
Bridge Ahead Signs Missing	0 1 (2)	
Brushing Required	Yes (No)	
Delinicator Missing Left	0 1 (2)	
Delinicator Missing Right	0 1 (2)	
Fender Condition	E G (F) P None UR	<u>logs covered in pile</u>
Posted Load Rating	(tonnes) or (None)	
Road Surface	E (G) F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Crib	E (G) F P N/A UR	
Tie-backs	E (G) F P N/A UR	
Bin Wall	E G F P (N/A) UR	
Concrete (cast in place; lock blocks, precast)	E G F P (N/A) UR	
Caps or Sills	E G F P (N/A) UR	
Piles or Posts	E G F P (N/A) UR	
Ballast Wall	E G F P (N/A) UR	
Wing Wall	E G F P (N/A) UR	
Bracing	E G F P (N/A) UR	
Hardware	E G (F) P N/A UR	<u>Loosen is loose</u>
Fill	E (G) F P N/A UR	
Riprap	E G F P (N/A) UR	<u>None</u>
Bearings	E (G) F P N/A UR	
Corrosion Protection	E G F P (N/A) UR	

Span 1 of 1 (spans are numbered consecutively starting from the left abutment)
Use "Additional Spans" Sheet for Multiple Spans**DECK**

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E G F P (N/A) UR	
Running Planks	E G F P (N/A) UR	
Sub-deck	E G F P (N/A) UR	
Ties	E G F P (N/A) UR	
Nails	E G F P (N/A) UR	
Deck to Girder Bolts	E G F P (N/A) UR	
Concrete Deck	E G F P (N/A) UR	
Grout Pockets	E G F P (N/A) UR	
Deck Joints	E G F P (N/A) UR	
Steel Deck Plate	E G F P (N/A) UR	
Gravel Surface	E G (F) P N/A UR	
Gravel Deck Depth	<u>0.3-0.4</u> metres or N/A	
Curb Rail/Blocks/Posts	E G F (P) UR	<u>None</u>
Handrails/ Walkouts	E G F P (N/A) UR	
Hardware	E G F P (N/A) UR	<u>Corroded</u>
Overall Deck Condition	E (G) F P UR	

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION***Site #: CK-200 7262

*Structure #:

SUPERSTRUCTURE (stringers numbered from upstream side of bridge)

Item		Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)			
Log Curb		E	G	P	UR		
Needle Beams and Shlms		E	G	F	P	N/A	UR
Stringer #	Wood Species	Peel'd? (circle)	Diameter (mm) or Width x Depth (mm x mm)		Rot Depth Bottom (mm)	Rot Depth Side (mm)	Rot Depth Top (mm)
1	CW	Y N	75 average		20-60		
2		Y N					
3		Y N					
4		Y N					
5		Y N					
6		Y N					
7		Y N					
8		Y N					
9		Y N					
10		Y N					

Stream CHANNEL*Est. Present Water Level Depth 1.2 (m)*Est. Present Water Level Width 10 (m)*Est. High Water Level Clearance 0.5 (m)**HAZARDS** (circle yes or no for each item)High Water? ☒ Yes ☐ No Scour? ☒ Yes ☐ No Ice? ☒ Yes ☐ No Debris? ☒ Yes ☐ No Aggradation? ☒ Yes ☐ No

Comments

REPAIRS:☐ Recommended☐ Not required (H = High, M = Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		Remove beaver dam
2	H M L		
3	H M L		

***Monitoring Status:**☐ Recommended☐ Not required

Monitor Item #	*Monitor Description
1	
2	

PHOTO LOG

Photo #	Description	Photo #	Description
1	LTR		
2	U/S		
3	d/s		
4	From U/S		

INSPECTOR TO COMPLETE THIS SECTION

As-built Drawings Checked?

Yes ☐ No ☒P Eng Inspection Required? Yes ☐ No ☒Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): 2005

(P Eng to review and evaluate inspector's estimate, and replace (year) on structure details screen in CBR as necessary)

*Date of Inspection (yyyy/mm/dd)

2011/11/09

*Inspection Company Name

Onsite Engineering

*Inspector's Name (print)

Jeremy ArakiInspector's Signature: 29756J. C. P. ARAKI

Inspector's Comments

Suggest downgrade - I would use 65cm ϕ to replace only 2 stringers. ALL IS SANDY AND THIN. STRINGERS ARE ALL VERY KNOTTY**PROFESSIONAL ENGINEER TO COMPLETE THIS SECTION**Current Load Rating GVW (tonnes): 20 tonnes

(P Eng to update structure details screen in CBR as necessary)

Date of Next Planned Inspection (yyyy/mm/dd) 2012/09/30

Reviewer Company Name

MoF

Reviewed by - P Eng's Name (print)

T. Miller

Reviewed by - P Eng's Signature

Date Reviewed (yyyy/mm/dd)

Jan 25, 2012

P Eng Reviewer's Comments

20 tonnes load rating; post load rating and bridge ahead signs.* Denotes Mandatory Information for Corporate Bridge Register
FS1337A HEG Oct. 18, 2010

Remove beaver dam and inspect in low water to properly assess cribs and stringers. Plan to replace entire structure soon.





CK2262 Downstream



CK2262 Left to Right Approach



CK2262 Right to Left Approach



CK2262 Upstream



CK2262 From Downstream 2



CK2262 From Upstream



CK2262 From Downstream