

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION**

(enter either long/lat or UTM below - not both)

*Site #: <u>CK-2263</u>	*Crossing Name: <u>Unknown</u>	*Type/Class: ☐ Major Culvert ☒ Woodbox/Log Culvert	*Project File ID# <u>8013</u>
*Structure #:			*Br. <u>01</u>
*FSR Name: <u>Stave River</u>	*Forest District: <u>CK</u>	*Kilometres: <u>11.4km</u>	User km:
Longitude: (ddd / mm / ss.s) <u>W122° 15' 23.0"</u>	OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>N49° 29' 28.0"</u>			UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	<u>(E)</u> G F P UR	
Bridge Ahead Signs Missing	0 1 <u>(2)</u>	
Brushing Required	Yes <u>(No)</u>	
Delineator Missing Left	<u>(0)</u> 1 <u>(2)</u>	
Delineator Missing Right	<u>(0)</u> 1 2	
Fender Condition	E G F P <u>(None)</u> UR	
Posted Load Rating	(tonnes) or <u>(None)</u>	
Road Surface	E G <u>(F)</u> P UR	<u>Hole in d/s fill</u>

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribs	E G <u>(F)</u> P N/A UR	<u>CAUSED IN WATER DUE TO BEARD DAM</u>
Tie-backs	E G <u>(F)</u> P N/A UR	
Bin Wall	E G F P <u>(N/A)</u> UR	
Concrete (cast in place; lock blocks, precast)	E G F P <u>(N/A)</u> UR	
Caps or Sills	E G <u>(F)</u> P N/A UR	
Piles or Posts	E G F P <u>(N/A)</u> UR	
Ballast Wall	E G F P <u>(N/A)</u> UR	
Wing Wall	E G F P <u>(N/A)</u> UR	
Bracing	E G F P <u>(N/A)</u> UR	
Hardware	E G F P <u>(N/A)</u> UR	
Fill	E G <u>(F)</u> P N/A UR	
Riprap	E G F P N/A UR	<u>CANNOT SEE</u>
Bearings	E G <u>(F)</u> P N/A UR	
Corrosion Protection	E G F P <u>(N/A)</u> UR	

Span 1 of 1 (spans are numbered consecutively starting from the left abutment)
Use "Additional Spans" Sheet for Multiple Spans**DECK**

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E G F P <u>(N/A)</u> UR	
Running Planks	E G F P <u>(N/A)</u> UR	
Sub-deck	E G F P <u>(N/A)</u> UR	
Ties	E G F P <u>(N/A)</u> UR	
Nails	E G F P <u>(N/A)</u> UR	
Deck to Girder Bolts	E G F P <u>(N/A)</u> UR	
Concrete Deck	E <u>(3)</u> F P <u>(N/A)</u> UR	
Grout Pockets	E G F P <u>(N/A)</u> UR	
Deck Joints	E G F P <u>(N/A)</u> UR	
Steel Deck Plate	E G F P <u>(N/A)</u> UR	
Gravel Surface	E G F <u>(P)</u> N/A UR	<u>Hole in d/s and gravel fill</u>
Gravel Deck Depth	<u>0.7</u> metres or N/A	
Curb Rail/Blocks/Posts	E G F <u>(P)</u> UR	<u>None</u>
Handrails/Walkouts	E G F P <u>(N/A)</u> UR	
Hardware	E G <u>(F)</u> P N/A UR	<u>LASTING WEAR</u>
Overall Deck Condition	E G F <u>(P)</u>	<u>HOLE IN FILL</u>

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION***Site #: CL-2263

*Structure #:

SUPERSTRUCTURE (stringers numbered from upstream side of bridge)

Item		Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)			
Log Curbs		E G F P <u>UR</u>		<u>Good</u>			
Needle Beams and Shims		E G F P <u>N/A</u> UR					
Stringer #	Wood Species	Peel? (circle)	Diameter (mm) or Width x Depth (mm x mm)	Rot Depth Bottom (mm)	Rot Depth Side (mm)	Rot Depth Top (mm)	Comments
1		Y N					
2		Y N					
3		Y N	SAME AS LAST				Broken stringer replaced
4		Y N	BUT BROKEN STRINGER				
5		Y N	LAST REPLACED				
6		Y N	COULD NOT ACCESS				
7		Y N	PROPERLY DUE TO BRACKET DAM				
8		Y N					Span = 11.5m
9		Y N					Gravel = 700mm
10		Y N					2009 Inspection Diameters

Stream CHANNEL*Est. Present Water Level Depth 1.7 (m) *Est. Present Water Level Width 10 (m) *Est. High Water Level Clearance 0.5 (m)**HAZARDS (circle yes or no for each item)**High Water? ☒ Yes ☐ No Scour? ☒ Yes ☐ No Ice? ☒ Yes ☐ No Debris? ☒ Yes ☐ No Aggradation? ☒ Yes ☐ No

Comments

REPAIRS:☒ Recommended☐ Not required (H = High, M = Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H <u>M</u> L		
2	<u>H</u> M L		REMOVE BEAVER DAMS
3	H M L		REPLACE FILL & ADD GEOTEXTILE

***Monitoring Status:**☐ Recommended☐ Not required

Monitor Item #	*Monitor Description
1	
2	

PHOTO LOG

Photo #	Description	Photo #	Description
1	Right		
2	Left		
3	From		

INSPECTOR TO COMPLETE THIS SECTIONAs-built Drawings Checked? ☐ Yes ☐ NoP Eng Inspection Required? ☐ Yes ☐ No

Inspector's Estimate of Full Log Haul Traffic Replacement Date (year):

(P Eng to review and evaluate inspector's estimate, and to provide Log Haul Traffic Replacement (year) on structure details screen in CBR)

*Date of Inspection (yyyy/mm/dd)

2011/11/09

*Inspection Company Name

Onsite Engineering

*Inspector's Name (print)

Jeremy ArakiInspector's Signature
J. C. P. ARAKI
29756

Inspector's Comments

PROFESSIONAL ENGINEER TO COMPLETE THIS SECTIONCurrent Load Rating GVW (tonnes): 54 tonnes

(P Eng to update structure details screen in CBR as necessary)

Date of Next Planned Inspection (yyyy/mm/dd)

2012/09/30

Reviewer Company Name

MoF

Reviewed by - P Eng's Name (print)

T. Miller

Reviewed by - P Eng's Signature

Date Reviewed (yyyy/mm/dd)

Jan 26, 2012



P Eng Reviewer's Comments

Remove beaver dam and assess cribs and stringers in summer of 2012.

* Denotes Mandatory Information for Corporate Bridge Register.
FS1337A HEG Oct. 18, 2010

2009 Inspection noted the cribs as poor.

Post bridge ahead and load rating signs. Pull gravel surfacing, lay geotextile to prevent surfacing from eroding and replace to a minimum depth of 600mm. Place curbs and log fenders. Present load rating of L60 or 54 tonnes to continue.





CK2263 Upstream



CK2263 Beaver dam at inlet



CK2263 From Downstream



CK2263 Left to Right Approach




CK2263 Right to Left Approach



CK2263 Hole in Fill



CK2263 From Upstream



CK2263 Hole in Fill is bigger below



CK2263 Left Abutment



CK2263 Broken Stringer that was removed