

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM below – not both)		
*Site #: <u>CK-2265</u>	*Crossing Name:	*Type/Class: ☐ Major Culvert ☒ Woodbox/Log Culvert	*Project File ID# <u>8013</u>			
*Structure #:			*Br. <u>01</u>			
*FSR Name: <u>Stave River</u>	*Forest District: <u>CK</u>	*Kilometres: <u>12.05</u>	User km:			
Longitude: (ddd / mm / ss.s) <u>W 122° 15' 55.7"</u>	<u>OR</u>	UTM Zone	UTM Easting	UTM Northing		
Latitude: (ddd / mm / ss.s) <u>N 49° 30' 15"</u>						
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated						
Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)				
Alignment	E ☒ F ☐ P ☐ UR	<u>straight & gentle</u>				
Bridge Ahead Signs Missing	0 1 ☒ 2					
Brushing Required	Yes ☐ No ☒					
Delineator Missing Left	☒ 1 ☐ 2					
Delineator Missing Right	☒ 1 ☐ 2					
Fender Condition	E ☒ F ☐ P ☐ None ☐ UR	<u>logs > 4" x 250mm above running surface</u>				
Posted Load Rating	(tonnes) or ☒ None					
Road Surface	E ☒ F ☐ P ☐ UR					
LEFT/RIGHT ABUTMENTS (as seen facing downstream)						
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)				
Log/Timber Cribbs	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Tie-backs	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Bin Wall	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Concrete (cast in place; lock blocks, precast)	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Caps or Sills	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Piles or Posts	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Ballast Wall	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Wing Wall	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Bracing	E ☐ G ☐ F ☐ P ☒ N/A ☐ UR					
Hardware	E ☐ G ☒ F ☐ P ☐ N/A ☐ UR	<u>Loose</u>				
Fill	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Riprap	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Bearings	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Corrosion Protection	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Span 1 of <u>1</u> (spans are numbered consecutively starting from the left abutment) Use "Additional Spans" Sheet for Multiple Spans						
DECK						
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)				
Running Surface (N/A if running surface is gravel or timber planks)	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Running Planks	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Sub-deck	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Ties	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Nails	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Deck to Girder Bolts	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Concrete Deck	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Grout Pockets	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Deck Joints	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Steel Deck Plate	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Gravel Surface	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Gravel Deck Depth	metres or N/A					
Curb Rail/Blocks/Posts	E ☐ G ☐ F ☐ P ☐ UR					
Handrails/Walkouts	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Hardware	E ☐ G ☐ F ☐ P ☐ N/A ☐ UR					
Overall Deck Condition	E ☐ G ☐ F ☐ P ☐ UR					

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION***Site #: CL-2265

*Structure #:

SUPERSTRUCTURE (stringers numbered from upstream side of bridge)

Item		Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)			
Log Curbs		E	G	<u>F</u>	P	UR	
Needle Beams and Shims		E	G	F	P	<u>N/A</u>	UR
Stringer #	Wood Species	Peel'd? (circle)	Diameter (mm) or Width x Depth (mm x mm)	Rot Depth Bottom (mm)	Rot Depth Side (mm)	Rot Depth Top (mm)	Comments
1		Y N					
2		Y N					
3		Y N					
4		Y N					
5		Y N					
6		Y N					
7		Y N					Span = 8.5m
8		Y N					Gravel = 500mm
9		Y N					2009 Inspection Diameters
10		Y N					

Stream CHANNEL

*Est. Present Water Level Depth ____ (m) *Est. Present Water Level Width ____ (m) *Est. High Water Level Clearance ____ (m)

HAZARDS (circle yes or no for each item)

High Water? Yes No Scour? Yes No Ice? Yes No Debris? Yes No Aggradation? Yes No

Comments

REPAIRS:☒ Recommended☐ Not required (H = High, M = Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		POST LOAD RATING
2	H M L		remove gravel fill, lay geotextile and backfill to 600mm depth
3	H M L		

***Monitoring Status:**☐ Recommended☐ Not required

Monitor Item #

*Monitor Description

1

2

PHOTO LOG

Photo #	Description	Photo #	Description
	From d/c		stringers
	Right bank		d/c
	Left bank		fill on bridge
	Fill below bridge		d/c

INSPECTOR TO COMPLETE THIS SECTIONAs-built Drawings Checked? Yes ☒ No ☐Paving Inspection Required? Yes ☐ No ☒Inspector's Estimate of Full Log Haul Traffic Replacement
Date (year): 2005
(PEng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR as necessary)

*Date of Inspection (yyyy/mm/dd)

2011/11/09

*Inspection Company Name

Onsite Engineers

*Inspector's Name (print)

Jeremy Araki

Inspector's Signature

Inspector's Comments

POST LOAD RATING - NOTE THAT NONE OF THESE HAUL FAILED AND ARE UNDER FULL LOADING. STILL SUGGEST THE 415 TONNES

PROFESSIONAL ENGINEER TO COMPLETE THIS SECTIONCurrent Load Rating GVW (tonnes): 41 tonnes

(PEng to update structure details screen in CBR as necessary)

Date of Next Planned Inspection (yyyy/mm/dd)

2012/09/30

Reviewer Company Name

MoF

Reviewed by - PEng (print)

T. Miller

Reviewed by - PEng's Signature

Date Reviewed (yyyy/mm/dd)
Jan 26, 2012


PEng Reviewer's Comments

Post bridge ahead and load rating signs.

Remove gravel fill, lay geotextile and backfill to 600mm depth.

* Denotes Mandatory Information for Corporate Bridge Register
FS1337A HEG Oct. 18, 2010

Present load rating of L45 or 41 tonnes to continue.





CK2265 Right Abutment



CK2265 Downstream



CK2265 Left Abutment




CK2265 From Downstream



CK2265 Upstream

CK2265 Fill that has failed...



CK2265 stringers where the fill...



CK2265 hole in fill





CK2265 Right to Left Approach



CK2265 Left to Right Approach