

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)**GENERAL INFORMATION**

(enter either long/lat or UTM below - not both)

*Site #: <u>CR-2270</u>	*Crossing Name:	*Type/Class: ☒ Temporary bridge ☐ Permanent bridge	*Project File ID# <u>8013</u>
*Structure #:			*Br. <u>01</u>
*FSR Name: <u>Star River</u>	*Forest District: <u>CIC</u>	*Kilometres:	User km:
Longitude: (ddd / mm / ss.s) <u>W 120° 20' 30.1"</u>	OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>N 49° 33' 52.2"</u>			UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G <u>P</u> UR	Right vertical → overtopper
Bridge Ahead Signs Missing	0 1 <u>2</u>	
Brushing Required	Yes <u>No</u>	
Delineator Missing Left	<u>0</u> 1 2	
Delineator Missing Right	<u>0</u> 1 2	
Fender Condition	E <u>G</u> F P None UR	Logs
Posted Load Rating	(tonnes) or <u>None</u>	
Road Surface	E <u>G</u> F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribs	E <u>G</u> F P N/A UR	
Tie-backs	E <u>G</u> F P N/A UR	
Bin Wall	E G F P <u>N/A</u> UR	
Concrete (cast in place; rock blocks, precast)	E G F P <u>N/A</u> UR	
Caps or Sills	E <u>G</u> F P N/A UR	Sill timbers
Piles or Posts	E G F P <u>N/A</u> UR	
Ballast Wall	E <u>G</u> F P N/A UR	Timber
Wing Wall	E G F P <u>N/A</u> UR	
Bracing	E G F P <u>N/A</u> UR	
Hardware	E G <u>P</u> P N/A UR	Loose, some loose
Fill	E <u>G</u> F P N/A UR	
Riprap	E <u>G</u> F P N/A UR	
Bearings	E G <u>P</u> P N/A UR	New bearing over old crib on two corners
Corrosion Protection	E G F P <u>N/A</u> UR	


Span 1 of 1 (spans are numbered consecutively starting from the left abutment)

Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E G F P <u>N/A</u> UR	
Running Planks	E <u>G</u> F P N/A UR	
Sub-deck	E G F P <u>N/A</u> UR	
Ties	E <u>G</u> F P N/A UR	
Nails	E <u>G</u> F P N/A UR	
Deck to Girder Bolts	E <u>G</u> F P N/A UR	Tabos
Concrete Deck	E G F P <u>N/A</u> UR	
Grout Pockets	E G F P <u>N/A</u> UR	
Deck Joints	E G F P <u>N/A</u> UR	
Steel Deck Plate	E G F P <u>N/A</u> UR	
Gravel Surface	E G F P <u>N/A</u> UR	
Gravel Deck Depth	metres or <u>N/A</u>	
Curb Rail/Blocks/Posts	E G <u>P</u> P UR	Some damage to right d/s
Handrails/Walkouts	E G F P <u>N/A</u> UR	
Hardware	E <u>G</u> F P N/A UR	
Overall Deck Condition	E <u>G</u> F P UR	

Routine Condition Bridge Inspection Form (except for log stringer or timber stringer bridges)


GENERAL INFORMATION			
*Site #: <u>CL-2270</u>		*Structure #:	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E <u>(G)</u> F P UR		
Diaphragms	E G F P <u>(N/A)</u> UR		
Bracing	E G F P <u>(N/A)</u> UR	<u>CAN NOT SEE BTWN GIRDERS</u>	
Under-trussing	E G F P <u>(N/A)</u> UR		
Hardware	E G F P <u>(N/A)</u> UR		
Welded / Grouted Shear Connectors	E G F P <u>(N/A)</u> UR		
Stream CHANNEL			
*Est. Present Water Level Depth <u>0.3</u> (m)		*Est. Present Water Level Width <u>5</u> (m)	*Est. High Water Level Clearance <u>1.3</u> (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes <u>(No)</u>	Scour?	Yes <u>(No)</u>
Ice?	Yes <u>(No)</u>	Debris?	Yes <u>(No)</u>
Aggradation?		Yes <u>(No)</u>	
Comments			
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		
2	H M L		
3	H M L		
*Monitoring Status: ☐ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1			
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	<u>L75</u>		<u>Guard rail damage</u>
	<u>Beam w/s</u>		<u>Right bracing</u>
	<u>right abut</u>		<u>Right abut</u>
	<u>left bearing</u>		<u>Left abut</u>
			<u>left about</u>
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes <u>(No)</u>		P Eng Inspection Required? Yes <u>(No)</u>	
Inspector's Comments		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): <u>2020</u> (PEng to review and evaluate Inspector's estimate, and to update Full Log Haul Traffic Replacement (year) on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd) <u>2011/11/09</u>	*Inspection Company Name <u>Onsite Engineering</u>	*Inspector's Name (print) <u>Jeremy Araki</u>	Inspector's Signature 
			
PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION			
Current Load Rating GVW (tonnes): <u>68 tonnes</u> (PEng to update structure details screen in CBR as necessary)		Date of Next Planned Inspection (yyyy/mm/dd) <u>2013/09/30</u>	
Reviewer Company Name <u>MoF</u>	Reviewed by - PEng's Name (print) <u>T. Miller</u>	Reviewed by - PEng's Signature 	Date Reviewed (yyyy/mm/dd) <u>Jan 26, 2012</u>
PEng Reviewer's Comment: <u>Steel identification indicates L75 or 68 tonnes rating,</u>			
send asbuilts for confirmation.			
* Denotes Mandatory Information for Corporate Bridge Register			
Repair damaged guardrail and post bridge ahead signs.			



CK2270 Right Abutment



CK2270 Left to Right Approach



CK2270 Left Bearing



CK2270 From Upstream



CK2270 Right to Left Approach



CK2270 Guard Rails



CK2270 Left Abutment



CK2270 Right Bearing



CK2270 Right Abutment Crip



CK2270 Girders