

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)


GENERAL INFORMATION			
*Site #: <u>CR 2308</u>	*Crossing Name: <u>Unknown</u>	*Type/Class: ☒ Temporary bridge ☐ Permanent bridge	(enter either long/lat or UTM below - not both) *Project File ID# <u>7972</u> *Br. <u>02</u>
*FSR Name: <u>VERLUS E ANDERSON</u>	*Forest District: <u>CR</u>	*Kilometres:	User km: <u>29.4</u>
Longitude: (ddd / mm / ss.s) <u>49° 43' 19.7"</u>	<u>OR</u>	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>121° 15' 18.6"</u>			UTM Northing
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated			
Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)	
Alignment	E G <u>(F)</u> P UR	<u>TIGHT CURVE</u>	
Bridge Ahead Signs Missing	0 1 <u>(2)</u>		
Brushing Required	<u>(Yes)</u> No	<u>MINOR</u>	
Delineator Missing Left	0 1 2		
Delineator Missing Right	0 1 <u>(2)</u>	<u>ALL 4 ARE LH DELINS</u>	
Fender Condition	E G F P <u>(None)</u> UR		
Posted Load Rating	(tonnes) or <u>(None)</u>		
Road Surface	E <u>(G)</u> F P UR		
LEFT/RIGHT ABUTMENTS (as seen facing downstream)			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Log/Timber Cribs	E G F <u>(P)</u> N/A UR	<u>UNDERMINED & OLD</u>	
Tie-backs	E G <u>(F)</u> P N/A UR		
Bin Wall	E G F P <u>(N/A)</u> UR		
Concrete (cast in place; rock blocks, precast)	E G F P <u>(N/A)</u> UR		
Caps or Sills	E G <u>(F)</u> P N/A UR	<u>LOGS SET BACK FROM OLD CRIBS - SEE BELOW</u>	
Piles or Posts	E G F P <u>(N/A)</u> UR		
Ballast Wall	E <u>(G)</u> F P N/A UR	<u>LOGS WRAPPED WITH GEOTEXTILE</u>	
Wing Wall	E G F P <u>(N/A)</u> UR		
Bracing	E G F P <u>(N/A)</u> UR		
Hardware	E G <u>(F)</u> P N/A UR		
Fill	E G <u>(F)</u> P N/A UR	<u>FAILED IN RIGHT U.S. CORNER</u>	
Riprap	E G F <u>(P)</u> N/A UR	<u>NONE UNDER BRIDGE</u>	
Bearings	E G F <u>(P)</u> N/A UR	<u>UNDERMINED ON L.S., RIGHT CORNER</u>	
Corrosion Protection	E G F P N/A UR		
Span 1 of <u>1</u> (spans are numbered consecutively starting from the left abutment) Use "Additional Spans" sheet for Multiple Spans			
DECK			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Running Surface (N/A if running surface is gravel or timber planks)	E G F P <u>(N/A)</u> UR		
Running Planks	E G <u>(F)</u> P N/A UR		
Sub-deck	E G F P <u>(N/A)</u> UR		
Ties	E G <u>(F)</u> P N/A UR		
Nails	E G <u>(F)</u> P N/A UR		
Deck to Girder Bolts	E G <u>(F)</u> P N/A UR		
Concrete Deck	E G F P <u>(N/A)</u> UR		
Grout Pockets	E G F P <u>(N/A)</u> UR		
Deck Joints	E G F P <u>(N/A)</u> UR		
Steel Deck Plate	E <u>(G)</u> F P <u>(N/A)</u> UR		
Gravel Surface	E G F P <u>(N/A)</u> UR		
Gravel Deck Depth	metres or <u>(N/A)</u>		
Curb Rail/Blocks/Posts	E G <u>(F)</u> P UR	<u>SOME DAMAGE - STEEL RISERS</u>	
Handrails/Walkouts	E G <u>(F)</u> P <u>(N/A)</u> UR		
Hardware	E <u>(G)</u> F P N/A UR		
Overall Deck Condition	E G <u>(F)</u> P UR		

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Site #: <u>OK 2308</u>		*Structure #:	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E (G) F P UR	CANNOT SEE UNDER - RIGHT ABUT	
Diaphragms	E G F P N/A UR	OLD LOG BRIDGE	
Bracing	E G F P N/A UR		
Under-trussing	E G F P N/A UR		
Hardware	E G F P N/A UR		
Welded / Grouted Shear Connectors	E G F P N/A UR		
Stream CHANNEL			
*Est. Present Water Level Depth <u>0.2</u> (m)		*Est. Present Water Level Width <u>3</u> (m)	*Est. High Water Level Clearance <u>2.5</u> (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes (No)	Scour?	Yes (No)
Ice?	Yes (No)	Dobris?	Yes (No)
Aggradation?	Yes (No)		
Comments			
REPAIRS:			
☒ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		FILL ON RIGHT - SUGGEST REMOVING & INSTALLING CN NEW ABUTMENTS
2	H M L		
3	H M L		
*Monitoring Status: ☒ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1	FILL ON RIGHT		
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	R-L		DS
	DECK FILL		LEFT BRACING
	L-R		BRIDGE ID
	US		GUARD RAIL
			FROM DS
			RIGHT CRIB
			RIGHT U.S. BRACING
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes (No)		P Eng Inspection Required? Yes (No)	
		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): <u>2005</u> (P Eng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd) <u>2011/11/11</u>	*Inspection Company Name <u>ONSITE ENG LTD</u>	*Inspector's Name (print) <u>Gregory ARAKI</u>	Inspector's Signature
Inspector's Comments <u>SEE REPAIRS</u>			
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION			
Current Load Rating GVW (tonnes): <u>5 tonnes</u> (P Eng to update structure details screen in CBR as necessary)		Date of Next Planned Inspection (yyyy/mm/dd) <u>2012/09/30</u>	
Reviewer Company Name <u>MoF</u>	Reviewed by - P Eng's Name (print) <u>T. Miller</u>	Reviewed by - P Eng's Signature 	Date Reviewed (yyyy/mm/dd) <u>2012/02/07</u>
P Eng Reviewer's Comments Due to undermined crib and failing fill under new sill, present load rating of 5 tonnes to continue.			

* Denotes Mandatory Information for Corporate Bridge Register

Agree with inspector, suggest remove and replace on new new abutments.



CK2308 Deck and Fill



CK2308 Bridge ID



CK2308 Left to Right Approach



CK2308 Right to Left Approach



CK2308 Left Abutment Bearing



CK2308 Upstream



CK2308 Girders



CK2308 Downstream



CK2308 Left Abutment Crib



CK2308 From Downstream




CK2308 Guard Rails



CK2308 Right Abutment Crib



CK2308 Right upstream fill



CK2308 Right upstream bearing