

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM below - not both)			
*Site #: <u>CK-2378</u>	*Crossing Name: <u>Winslow Side Channel</u>	*Type/Class: ☐ Temporary bridge ☒ Permanent bridge	*Project File ID# <u>2013</u>				
*Structure #:			*Br. <u>01</u>				
*FSR Name: <u>Stave River</u>	*Forest District: <u>CK</u>	*Kilometres:	User km: <u>17.7</u>				
Longitude: (ddd / mm / ss.s) <u>w122° 14' 20.3"</u>	OR	UTM Zone	UTM Easting	UTM Northing			
Latitude: (ddd / mm / ss.s) <u>N49° 28' 38.6"</u>							

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G F <u>P</u> UR	Tripod vertical on right side
Bridge Ahead Signs Missing	0 1 <u>2</u>	
Brushing Required	Yes <u>No</u>	
Delineator Missing Left	<u>0</u> 1 2	
Delineator Missing Right	<u>0</u> 1 2	
Fender Condition	E <u>G</u> F P None UR	N3B,
Posted Load Rating	(tonnes) of <u>None</u>	(L-75 ON BRIDGE)
Road Surface	E <u>G</u> F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribs	E G F P <u>N/A</u> UR	
Tie-backs	E G F P <u>N/A</u> UR	
Bin Wall	E G F P <u>N/A</u> UR	
Concrete (cast in place, block blocks, precast)	E G F P <u>N/A</u> UR	
Caps or Sills	E <u>G</u> F P N/A UR	
Piles or Posts	E <u>G</u> F P N/A UR	
Ballast Wall	E G F <u>P</u> N/A UR	LEFT GOOD/LIGHT HAS, EXPOSED REPAIR
Wing Wall	E G F P <u>N/A</u> UR	
Bracing	E <u>G</u> F P N/A UR	
Hardware	1: <u>G</u> F P N/A UR	
Fill	E G F <u>P</u> N/A UR	FAILING ON D.S. RIGHT ABUT
Riprap	E <u>G</u> F P N/A UR	
Bearings	E <u>G</u> F P N/A UR	
Corrosion Protection	E <u>12</u> F P N/A UR	

Span 1 of 1 (spans are numbered consecutively starting from the left abutment)
Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E <u>G</u> F P N/A UR	
Running Planks	E G F P <u>N/A</u> UR	
Sub-deck	E G F P <u>N/A</u> UR	
Ties	E G F <u>1</u> N/A UR	
Nails	E G F P <u>N/A</u> UR	
Deck to Girder Bolts	E G F P N/A UR	
Concrete Deck	E G F P <u>N/A</u> UR	
Grout Pockets	E <u>G</u> F P N/A UR	
Deck Joints	E G F <u>P</u> N/A UR	No foam/Filler
Steel Deck Plate	E G F P <u>N/A</u> UR	
Gravel Surface	E G F P <u>N/A</u> UR	
Gravel Deck Depth	metres or <u>N/A</u>	
Curb Rail/Blocks/Posts	E <u>G</u> F P UR	
Handrails/ Walkouts	E <u>G</u> F P N/A <u>1</u> ?	
Hardware	E <u>G</u> F P N/A UR	
Overall Deck Condition	E <u>G</u> F P UR	

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Site #: <u>CL-237B</u>		*Structure #:	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E (G) F P UR		
Diaphragms	E G F P (N/A) UR		
Bracing	E (G) F P (N/A) UR		
Under-trussing	E G F P (N/A) UR		
Hardware	E (G) F P (N/A) UR		
Welded / Grouded Shear Connectors	E G F P (N/A) UR		
Stream CHANNEL			
*Est. Present Water Level Depth <u>2.1</u> (m)		*Est. Present Water Level Width <u>20</u> (m)	*Est. High Water Level Clearance <u>2</u> (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes (No)	Scour?	Yes (No)
Ice?	Yes (No)	Debris?	Yes (No)
Aggradation?	Yes (No)		
Comments			
REPAIRS: ☒ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	(H) M L		FIX FILL ON RIGHT
2	H M L		- ADD ROCK AT BOTTOM AND THEN FILL
3	(H) M L		- CONSIDER TESTS
GROUT OVER REBAR IN BALLAST WALL ON RIGHT			
*Monitoring Status: ☐ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1			
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	FROM D/S		LEFT BRACING
	RIGHT ABUT		D.S
	BRIDGE ID		GIRDERS
	LEFT ABUT		L.S
			DECK CLIPS
			RIGHT DS FILL
			LEFT TO RIGHT
			R - LEFT
			REBAR EXPOSED ON RIGHT BALLAST
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes (No)		P Eng Inspection Required? Yes (No)	
		Inspector's Estimate of Full Log Haul Traffic Replacement	
		Date (year): <u>2050</u>	
		(P Eng to review and evaluate Inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details sketch in CBR)	
*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature
<u>2011/11/09</u>	<u>Onsite Engineering</u>	<u>Jeremy Araki</u>	
Inspector's Comments			
PROFESSIONAL ENGINEER (PENG) TO COMPLETE THIS SECTION			
Current Load Rating GVW (tonnes): <u>68 tonnes</u>		Date of Next Planned Inspection (yyyy/mm/dd): <u>2014/09/30</u>	
(P Eng to update structure details sketch in CBR as necessary)			
Reviewer Company Name	Reviewed by - P Eng's Name (print)	Reviewed by - P Eng's Signature	Date Reviewed (yyyy/mm/dd)
<u>MoF</u>	<u>T. Miller</u>		<u>2012/05/08</u>
P Eng Reviewer's Comments			
See repair items noted above. Post bridge ahead signs.			
* Denotes Mandatory Information for Corporate Bridge Register			
Present load rating of L75 or 68 tonnes to continue.			



CK2378 Right Abutment



CK2378 Bridge ID



CK2378 Left Rip Rap




CK2378 From Downstream



CK2378 Deck clips



CK2378 Left Abutment



CK2378 Left to Right Approach



CK2378 Girders



CK2378 Right Abutment fill



CK2378 Downstream



CK2378 Right to Left Approach



CK2378 Upstream



CK2378 Right ballast wall damage