



BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

GENERAL	
*Structure # <u>CK2231</u>	*Site #: <u>CK2231</u>
*Type/Class: ☒ Permanent Bridge ☐ Temporary Bridge	Crossing Name: <u>SECOND CANYON PITT RIVER</u>
*Forest District: <u>CHILLIWACK</u>	Management Area:
*Forest Service Road: <u>PITT BUCKLIN</u>	Kilometres: <u>0.8</u>
*Project File ID#: <u>8394</u>	*Br. <u>03</u>
Built For: ☐ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ Other Ministry ☐ Inherited: Non-Status Road ☐ Inherited: Transfers from Other Ministries ☐ Inherited: Reallocation ☐ New Structure ☐ Replacement Structure	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): <small>(PEng to enter / update this value on structure details screen in CBR)</small>	Design Load Rating GVW (tonnes): <small>(Typically obtained from design drawings)</small>
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): <small>(PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).</small>
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR)
Structure Inventory Data Form "BRIDGES"

STRUCTURAL DETAILS CK-2251			
Number of Spans: 3		Length of Spans (m) [e.g. for a 3-span bridge – 20, 35, 20] 18.3, 17.7, 21.6	
Number of Piers: 2		Pier Type: ☒ Concrete ☐ Crib - Timber ☐ Piles - Concrete ☐ Piles - Steel ☐ Piles - Timber Treated ☐ Piles - Timber Untreated ☐ Steel Column on Concrete Pad	
Needle Beams? ☐ Yes ☒ No		Portable Structure? ☐ Yes ☒ No	Portable Superstructure Status: ☐ Installed ☐ Storage
Portable Superstructure Storage Location:			
*Bridge Length (metres): 57.6	*Superstructure: ☐ Compo Girders ☐ Concrete Box Beam ☐ Rail Car ☐ Concrete Cast in Place ☐ Concrete I/T Beam ☐ Other ☐ Concrete Slab Girders ☐ Glulam Girder ☐ Log Stringer ☐ Steel Box Beam ☒ Steel I-Beam ☐ Steel Truss/Bailey/Acrow ☐ Timber-Treated Stringers ☐ Timber-Untreated Stringers		
*Deck Type: ☐ Concrete ☒ Concrete Composite ☐ Gravel ☐ Concrete Removable ☐ Concrete - Steel Free ☐ Steel ☐ Timber-Treated ☐ Timber-Untreated ☐ Other ☐ Timber-Treated Panels ☐ Timber-Untreated Panels			*Deck Width (metres): 4.8
*Running Surface: ☐ Anti-Skid ☐ Asphalt ☒ Concrete ☐ Gravel ☐ Not Available ☐ Timber Planks			
*Left Abutment: ☐ Binwall ☒ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☐ Steel Pipe & Precast Pad		*Right Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad	
Comments:			

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION - multi span -		(enter either long/lat or UTM below - not both)	
*Site #: CK 2231	*Crossing Name: SECOND CANYON PITT AV	*Type/Class: ☐ Temporary bridge ☒ Permanent bridge	*Project File ID# 8394
*Structure #: CK 2231	*Forest District: CHILWICK	*Kilometres: 0.8	*Br. 03
*FSR Name: PITT BUCKLIN	*Forest District: CHILWICK	*User km: 0.8	
Longitude: (ddd / mm / ss.s)	OR UTM Zone	UTM Easting	UTM Northing
Latitude: (ddd / mm / ss.s)			
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated			
Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)	
Alignment	E G F (P) UR	Very tight hor. curve	
Bridge Ahead Signs Missing	0 1 (2)		
Brushing Required	Yes (No)		
Delineator Missing Left	(0) 1 2		
Delineator Missing Right	(0) 1 2		
Fender Condition	E G (F) P None UR	LOSS	
Posted Load Rating	(tonnes) or None	not posted.	
Road Surface	E (G) F P UR		
LEFT/RIGHT ABUTMENTS (as seen facing downstream)			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Log/Timber Cribs	E G (F) P N/A UR	OK crib retain fill in front of riprap.	
Tie-backs	E G (F) P N/A UR	Just retaining fill	
Bin Wall	E G F P (N/A) UR		
Concrete (cast in place; lock blocks, precast)	E G (P) P N/A UR	CRST IN PLACE	
Caps or Sills	E G F P (N/A) UR		
Piles or Posts	E (G) F P N/A UR	→ Right abut.	
Ballast Wall	E (G) F P N/A UR		
Wing Wall	E G (F) P N/A UR	OK right abut.	
Bracing	E (G) F P N/A UR		
Hardware	E (G) F P N/A UR		
Fill	E G F (P) N/A UR	The fill in front of left abut is failing.	
Riprap	E G F P (N/A) UR	B/R controlled.	
Bearings	E (G) F P N/A UR		
Corrosion Protection	E G F P (N/A) UR		
Span 1 of 3 (spans are numbered consecutively starting from the left abutment) Use "Additional Spans" Sheet for Multiple Spans			
DECK			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Running Surface (N/A if running surface is gravel or timber planks)	E (G) F P N/A UR		
Running Planks	E G F P (N/A) UR		
Sub-deck	E G F P (N/A) UR		
Ties	E G F P (N/A) UR		
Nails	E G F P (N/A) UR		
Deck to Girder Bolts	E G F P (N/A) UR		
Concrete Deck	E G (F) P N/A UR	Sewer - comp.	
Grout Pockets	E G (F) P N/A UR		
Deck Joints	E G (F) P N/A UR		
Steel Deck Plate	E G F P (N/A) UR		
Gravel Surface	E G F P (N/A) UR		
Gravel Deck Depth	metres or (N/A)		
Curb Rail/Blocks/Posts	E (G) F P UR	Repair curb post Insp	
Handrails/ Walkouts	E G F P (N/A) UR		
Hardware	E (G) F P N/A UR		
Overall Deck Condition	E (G) F P UR		

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Site #: CK 2231		*Structure #: CK 2231	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E G <u>P</u> UR		
Diaphragms	E G F P <u>N/A</u> UR		
Bracing	E G <u>P</u> N/A UR		
Under-trussing	E G F P <u>N/A</u> UR		
Hardware	E G <u>P</u> N/A UR	Bolted Connections	
Welded / Grouted Shear Connectors	E G F P <u>N/A</u> UR		
Stream CHANNEL			
*Est. Present Water Level Depth 2 (m)		*Est. Present Water Level Width 20 (m)	*Est. High Water Level Clearance 5 (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes <u>No</u>	Scour?	Yes <u>No</u>
Ice?	Yes <u>No</u>	Debris?	Yes <u>No</u>
Aggradation?	Yes <u>No</u>		
Comments Left abut.			
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		
2	H M L		
3	H M L		
*Monitoring Status: ☒ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1	Footings Scour - Left abutment.		
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	From D/S		Pier #2 x 3
	L to R		Left abut V 3
	R to L		Right abut R 2
	Pier #1 A 2		
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes <u>No</u>		P Eng Inspection Required? Yes <u>No</u>	
		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): (P Eng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd) 2012-08-24	*Inspection Company Name Onsite Eng	*Inspector's Name (print) Ali Sodeghin	Inspector's Signature
Inspector's Comments check asbuilt to ensure left footing installed on B/C. The fill in front of footing is failing (large hole present)			
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION			
Current Load Rating GWV (tonnes): 109 tonnes (P Eng to update structure details screen in CBR as necessary)		Date of Next Planned Inspection (yyyy/mm/dd) 2015/09/30 and could impact stability of footing.	
Reviewer Company Name MoF	Reviewed by - P Eng's Name (print) T. Miller	Reviewed by - P Eng's Signature 	Date Reviewed (yyyy/mm/dd) 2013/02/21
P Eng Reviewer's Comments Present load rating of L120 or 109 tonnes to continue.			

* Denotes Mandatory Information for Corporate Bridge Register

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)**USE THIS SHEET FOR ADDITIONAL SPANS****GENERAL INFORMATION**Site # 0000000000 CK 2231Structure # 0000000000Span 1 of 3 (spans are numbered consecutively starting from the left abutment)**DECK**

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E <u>G</u> F P N/A UR	
Running Planks	E G F P <u>N/A</u> UR	
Sub-deck	E G F P <u>N/A</u> UR	
Ties	E G F P <u>N/A</u> UR	
Nails	E G F P <u>N/A</u> UR	
Deck to Girder Bolts	E G F P <u>N/A</u> UR	
Concrete Deck	E G <u>F</u> P N/A UR	
Grout Pockets	E G <u>F</u> P N/A UR	
Deck Joints	E G <u>F</u> P N/A UR	
Steel Deck Plate	E G F P <u>N/A</u> UR	
Gravel Surface	E G F P <u>N/A</u> UR	
Gravel Deck Depth	metres or <u>N/A</u>	
Curb Rail/Blocks/Posts	E <u>G</u> F P UR	
Handrails/ Walkouts	E G F P <u>N/A</u> UR	
Hardware	E <u>G</u> F P N/A UR	
Overall Deck Condition	E <u>G</u> F P UR	

SUPERSTRUCTURE

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Girders	E <u>G</u> F P UR	
Diaphragms	E G F P <u>N/A</u> UR	
Bracing	E <u>G</u> F P N/A UR	
Under-trussing	E G F P <u>N/A</u> UR	
Hardware	E <u>G</u> F P N/A UR	Painted Connections
Welded / Grouted Shear Connectors	E G F P <u>N/A</u> UR	

PIER 1 of 2 (piers are numbered consecutively starting from the left abutment)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Caps	E <u>G</u> F P UR	
Piles or Posts	E G F P <u>N/A</u> UR	
Concrete	E <u>G</u> F P N/A UR	
Bracing or Sheathing	E G F P <u>N/A</u> UR	
Cribs	E G F P <u>N/A</u> UR	
Hardware	E G F P N/A <u>UR</u>	
Rip Rap	E G F P <u>N/A</u> UR	no rip rap
Dolphins	E G F P <u>N/A</u> UR	
Bearings	E <u>G</u> F P N/A UR	
Wall	E G F P <u>N/A</u> UR	
Overall	E <u>G</u> F P UR	

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)**USE THIS SHEET FOR ADDITIONAL SPANS**


GENERAL INFORMATION		
Site #	CL 2 231	
Structure #		
Span	3 of 3 (spans are numbered consecutively starting from the left abutment)	
DECK		
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E <u>G</u> F P N/A UR	
Running Planks	E G F P <u>N/A</u> UR	
Sub-deck	E G F P <u>N/A</u> UR	
Ties	E G F P <u>N/A</u> UR	
Nails	E G F P <u>N/A</u> UR	
Deck to Girder Bolts	E G F P <u>N/A</u> UR	
Concrete Deck	E G <u>F</u> P N/A UR	
Grout Pockets	E G <u>F</u> P N/A UR	
Deck Joints	E G <u>F</u> P N/A UR	
Steel Deck Plate	E G F P <u>N/A</u> UR	
Gravel Surface	E G F P <u>N/A</u> UR	
Gravel Deck Depth	metres or <u>N/A</u>	
Curb Rail/Blocks/Posts	E <u>G</u> F P UR	
Handrails/ Walkouts	E G F P <u>N/A</u> UR	
Hardware	E <u>G</u> F P N/A UR	
Overall Deck Condition	E <u>G</u> F P UR	
SUPERSTRUCTURE		
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Girders	E <u>G</u> F P UR	
Diaphragms	E G F P <u>N/A</u> UR	
Bracing	E <u>G</u> F P N/A UR	
Under-trussing	E G F P <u>N/A</u> UR	
Hardware	E <u>G</u> F P N/A UR	Initial connection
Welded / Grouted Shear Connectors	E G F P <u>N/A</u> UR	
PIER 2 of 2 (piers are numbered consecutively starting from the left abutment)		
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Caps	E <u>G</u> F P UR	
Piles or Posts	E G F P <u>N/A</u> UR	
Concrete	E <u>G</u> F P N/A UR	
Bracing or Sheathing	E G F P <u>N/A</u> UR	
Cribs	E G F P <u>N/A</u> UR	
Hardware	E G F P N/A <u>UR</u>	
Rip Rap	E G F P <u>N/A</u> UR	new rip rap
Dolphins	E G F P <u>N/A</u> UR	
Bearings	E <u>G</u> F P N/A UR	
Wall	E G F P <u>N/A</u> UR	
Overall	E <u>G</u> F P UR	



CK2231 Left to Right



CK2231 From Downstream



CK2231 Right Abutment



CK2231 View of Upstream



CK2231 pier2 (2)



CK2231 pier2



CK2231 pier2 (1)



CK2231 pier1 (1)



CK2231 Left Abutment (3)



CK2231 Right Abutment (2)



CK2231 Left Abutment (1)



CK2231 Right to Left



CK2231 Left Abutment (2)



CK2231 pier1 (2)