



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3

Date Printed: 2013/08/30

User Id: IDIRITYSMILLE

Database: PROD

Report Id: CBR001B

Structure #:	CK-2090	Site #:	CK-2090	Road Name:	DEWDNEY SIX	Inspection Date:	2013/08/28
KM:	0.00	User km:	0.00	Crossing Name:	Coquihalla River	Next Inspection Date:	2015/08/28
Project File ID #:	7995	Br.	06	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel Truss/Bailey/Acrow			Abutments (Left/Right):	Concrete Precast		
Total Length (metres):	40.9	# Spans:	1	Span Length(s) (metres):	40.1		
UTM Zone:	10	UTM Easting:	626726	UTM Northing:	5482535		
Inspector Name:	T. Miller			Year Built:	1991		
Access:	Driving east from Hope Highway #5, turn right onto Dewdney Temp.						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	tight HC at both approaches
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	but minor
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	Good	
Posted Load Rating	54	
Road Surface	Good	

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/08/30
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2090	Site #:	CK-2090	Road Name:	DEWDNEY SIX	Inspection Date:	2013/08/28			
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Unrated	NA								
Ties	Good	treated 100mm x 300mm								
SUPERSTRUCTURE										
Span 1										
Bracing	Fair									
Diaphragms	Fair									
Girders	Fair	triple single acrow panel, 13 panels								
Hardware	Fair									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	20.0						
	Estimated High Water Level Clearance:	3.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Recommended	Medium	\$1.00	install bridge ahead signs					
	2	Recommended	Medium	\$1.00	brush with activity					
MONITORS	#	Description								
	1	pins for movement								
	2	Bow in deck								
GENERAL	Professional Inspection Required?	No	Regional Review Date:	2013/08/30	P. Eng Reviewer Name:	Tyson Miller				
	Replacement Date for full log haul traffic (year):	2021	Replacement Date for light vehicle traffic (year):	2021						
	Current Load Rating GVW (tonnes):	54	Design Load GVW (tonnes):	54	Design Vehicle Config.:	L60				
	Inspector's Estimated Full Log Haul Replacement (year):									
	Inspector's Comment:	No movement in steel stringers with repair work completed in 2011.								
Corporate Bridge Register (CBR)										



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/08/30
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2090	Site #:	CK-2090	Road Name:	DEWDNEY SIX	Inspection Date:	2013/08/28
PEng Reviewer's Comment:	Post bridge ahead signs and brush with activity. Monitor pins for movement. Present load rating of L60 or 54 tonnes to continue.						
District Staff Comment:							

*Bill
Aug 30/2013*







