



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/08/27
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2110	Site #:	CK-2110	Road Name:	HARRISON EAST	Inspection Date:	2013/07/04
KM:	40.50	User km:	38.50	Crossing Name:	Clear Creek (structure # 29)	Next Inspection Date:	2014/07/04
Project File ID #:	5748	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right):	Crib, Log or Untreated Timber		
Total Length (metres):	18.7	# Spans:	1	Span Length(s) (metres):	0		
UTM Zone:	10	UTM Easting:	583986	UTM Northing:	5499165		
Inspector Name:	T. Miller			Year Built:	1985		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	fair to poor, no crushing evident
Fill	Fair	drift pins evident
Hardware	Fair	
Log/Timber Crib	Poor	fair to poor, no signs of crushing, left D/S scoured
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Poor	4x - significant rot in some, no movement evident since last year
Wing Wall	Poor	right U/S rotting; left D/S rotting

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left	1	
Delineator Missing Right	1	
Fender Condition	Good	
Posted Load Rating	68	
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	undersized at 200mm x 200mm
------------------------	------	-----------------------------



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/08/27
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2110	Site #:	CK-2110	Road Name:	HARRISON EAST	Inspection Date:	2013/07/04				
Deck to Girder Bolts	Fair										
Hardware	Fair										
Hand Rails/Walkouts	Not Applicable										
Nails	Fair										
Overall Deck Condition	Fair										
Running Planks	Fair			not staggered - full width							
Sub Deck	Fair			creosoted							
Ties	Fair			creosoted							
SUPERSTRUCTURE											
Span 1											
Bracing	Fair			bolted, surface rust							
Diaphragms	Fair			bolted, surface rust							
Girders	Fair			2 steel I-beams, surface rust							
Hardware	Fair										
Under Trussing	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		1.0	Estimated Present Water Level Width:		10.0					
	Estimated High Water Level Clearance:		3.0								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	Medium	\$1.00	replace missing delineators						
MONITORS	#	Description									
	3	both abutments for settlement									
	4	void under downstream left abutment									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/08/27	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):			2013	Replacement Date for light vehicle traffic (year):			2015			
	Current Load Rating GVW (tonnes):		68	Design Load GVW (tonnes):		127	Design Vehicle Config.:		Other		
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
Corporate Bridge Register (CBR)											



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/08/27
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2110	Site #:	CK-2110	Road Name:	HARRISON EAST	Inspection Date:	2013/07/04
PEng Reviewer's Comment:	Replace missing delineators. Monitor both abutments for settlement, especially when hauling. Monitor void on left downstream abutment and plan for replacement soon. Present load rating of L75 or 68 tonnes to continue.						
District Staff Comment:							

T. Miller
Aug 27/2013





SINGLE
LANE
BRIDGE
BRIDGE
LOAD LIMIT
68,040
NO GVW





