



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2013/08/27
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001C

Structure #:	CK-2125	Site #:	CK-2125	Road Name:	SHOVEL CREEK	Inspection Date:	2013/07/04
KM:	11.10	User km:	11.10	Crossing Name:	Not Known	Next Inspection Date:	2016/07/04
Project File ID #:	5748	Br.	06	Forest District:	Chilliwack Forest District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	5,000			Outlet Cover (mm):	8,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	589306	UTM Northing:	5520734		
Inspector Name:	T. Miller			Year Built:	1990		
Access:	Drive on road north of Harrison Hot springs. This road connects with Harrison East FSR. Turn Right off of Harrison East FSR onto Harrison East -Shovel Creek FSR						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	None	
Posted Load Rating	not	not posted
Road Surface	Fair	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Fair	5m cover at inlet, some erosion evident - 8 meter cover at outlet
Floor	Fair	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	concrete apron
Outlet	Fair	1 meter drop into pool, some undermining
Overall	Fair	
Riprap	Fair	some riprap has eroded at inlet
Roof	Fair	



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2013/08/27
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001C

Structure #:	CK-2125	Site #:	CK-2125	Road Name:	SHOVEL CREEK	Inspection Date:	2013/07/04			
Side Walls	Fair									
Trash Rack	Fair	top of rack is exposed								
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	5.0						
	Estimated High Water Level Clearance:	0.0								
HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Recommended	Medium	\$1.00	replace missing riprap at inlet to protect exposed rack support					
MONITORS	#	Description								
	1	monitor undermining culvert at outlet								
GENERAL	Professional Inspection Required?	No	Regional Review Date:	2013/08/27	P. Eng Reviewer Name:	Tyson Miller				
	Replacement Date for full log haul traffic (year):	2010	Replacement Date for light vehicle traffic (year):							
	Current Load Rating GVW (tonnes):	136	Design Load GVW (tonnes):	136	Design Vehicle Config.:	L150				
	Inspector's Estimated Full Log Haul Replacement (year):									
	Inspector's Comment:									
	PEng Reviewer's Comment:	Replace riprap at inlet to protect exposed trash rack support. Monitor outlet for further undermining. Present load rating of L150 or 136 tonnes to continue.								
	District Staff Comment:									
<div style="text-align: center;"></div>										
Corporate Bridge Register (CBR)										





