



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/09/27
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2157	Site #:	CK-2157	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05
KM:	2.20	User km:	2.20	Crossing Name:	Hunter Creek	Next Inspection Date:	2014/09/05
Project File ID #:	6086	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right):	Crib, Log or Untreated Timber		
Total Length (metres):	32.9	# Spans:	1	Span Length(s) (metres):	32.1		
UTM Zone:	10	UTM Easting:	604015	UTM Northing:	5466588		
Inspector Name:	T. Miller			Year Built:	1986		
Access:	Driving east from Chilliwack on Highway #1 turn right onto Lorenzetta-Hunter Creek FSR						

ABUTMENTS

Bearings	Fair	on right abutment the steel girders bear just in front of Center of crib (100mm). The even bearing is dependent of the tiebacks - monitor annually for settlement especially while hauling
Bracing	Not Applicable	
Ballast Wall	Fair	logs
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	steel I-beam on creosoted timbers - I-beam bolted to timbers and steel girders
Fill	Fair	
Hardware	Poor	no lashing visible
Log/Timber Cribs	Fair	3x
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Fair	some pocket rot detected - 6x but bearing between 4
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	None	
Posted Load Rating	not	posted
Road Surface	Fair	

DECK

Span 1



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/09/27
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2157	Site #:	CK-2157	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05			
Curb Rail/Blocks/Posts	Fair	minor damage on downstream right approach - riser only on 1 tie								
Deck to Girder Bolts	Fair									
Hardware	Fair	rail bolts getting loose								
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Fair									
Running Planks	Fair									
Sub Deck	Fair	treated								
Ties	Good	treated								
SUPERSTRUCTURE										
Span 1										
Bracing	Fair	between each diaphragm - bolted								
Diaphragms	Fair	11 bays - bolted and galvanized								
Girders	Fair	2 steel I-beams								
Hardware	Fair									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		10.0			
	Estimated High Water Level Clearance:		4.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Recommended	High	\$1.00	install log fenders					
	2	Recommended	Medium	\$1.00	post bridge ahead and load rating signs					
MONITORS	#	Description								
	1	abutments								
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/09/27	P. Eng Reviewer Name:		Tyson Miller	
	Replacement Date for full log haul traffic (year):			2006	Replacement Date for light vehicle traffic (year):					
	Current Load Rating GVW (tonnes):		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:		L60	
	Inspector's Estimated Full Log Haul Replacement (year):									
	Inspector's Comment:									
Corporate Bridge Register (CBR)										



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/09/27
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2157	Site #:	CK-2157	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05
PEng Reviewer's Comment:	Place log fenders prior to industrial activity and post bridge ahead and load rating signs. Monitor abutment condition especially while hauling. Present load rating of L60 or 54 tonnes to continue.						
District Staff Comment:							



Till
Sept 27/2013





