



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/09/13
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2158	Site #:	CK-2158	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05
KM:	4.90	User km:	4.90	Crossing Name:	East Fork Hunter Creek	Next Inspection Date:	2014/09/05
Project File ID #:	6086	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right):	Concrete Cast in Place/Concrete Lock Block		
Total Length (metres):	21.4	# Spans:	1	Span Length(s) (metres):	20.8		
UTM Zone:	10	UTM Easting:	605769	UTM Northing:	5464996		
Inspector Name:	T. Miller		Year Built:	2002			
Access:	Driving East from Chilliwack on Highway #1 turn right onto Lorezetta-Hunter Creek FSR Updated by M.Kirk, Onsite Engineering Ltd, Jan 2011						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	timbers
Concrete Cast in Place	Fair	right side
Concrete Lock Blocks	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	timbers
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	scour noted left side
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	HC both approaches
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left	0	
Delineator Missing Right	1	
Fender Condition	Fair	
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	steel riser bolted to ties, and some ties have sheared
------------------------	------	--



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/09/13
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2158	Site #:	CK-2158	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05				
Deck to Girder Bolts	Poor	losse									
Hardware	Poor	loose									
Hand Rails/Walkouts	Not Applicable										
Nails	Poor	protruding									
Overall Deck Condition	Poor	replace deck									
Running Planks	Fair										
Sub Deck	Poor	none									
Ties	Poor	rotten									
SUPERSTRUCTURE											
Span 1											
Bracing	Fair										
Diaphragms	Fair	6 bays - welded									
Girders	Fair	2 steel I-beams									
Hardware	Not Applicable										
Under Trussing	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.4		Estimated Present Water Level Width:		6.0				
	Estimated High Water Level Clearance:		4.0								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	High	\$1.00	replace ties, subdeck, wear planks and guardrail						
	2	Recommended	High	\$1.00	post load rating						
	3	Recommended	Medium	\$1.00	post bridge ahead sign and missing delineator						
MONITORS	#	Description									
	1	left abutment									
	2	hairline cracks in CIP									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/09/13	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):			2042		Replacement Date for light vehicle traffic (year):			2042		
	Current Load Rating GVW (tonnes):		5		Design Load GVW (tonnes):		68		Design Vehicle Config.:		L75
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
Corporate Bridge Register (CBR)											



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/09/13
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2158	Site #:	CK-2158	Road Name:	LORENZETTA HUNTER	Inspection Date:	2013/09/05
PEng Reviewer's Comment:	Replace ties, subdeck, wear planks and guardrail system prior to use. Install bridge ahead sign and missing delineator. Monitor scour noted on left riprap and cracks on CIP abutment. 5 tonnes load limit until deck and guardrail replaced, please post.						
District Staff Comment:							

T. W. Miller
Sept 13/2013













