



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 4

Date Printed: 2013/12/19

User Id: IDIR\TYSMILLE

Database: PROD

Report Id: CBR001A

Structure #:	CK-2196	Site #:	CK-2196	Road Name:	NAHATLATCH	Inspection Date:	2013/10/01
KM:	0.80	User km:	0.80	Crossing Name:	Nahatlatch River	Next Inspection Date:	2014/10/01
Project File ID #:	6996	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right):	Concrete Cast in Place		
Total Length (metres):	71.3	# Spans:	3	Span Length(s) (metres):	16.1, 40, 15.2		
UTM Zone:	10	UTM Easting:	605917	UTM Northing:	5537381		
Inspector Name:	T. Miller		Year Built:	1987			
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Jan 2011						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	treated timbers
Concrete Cast in Place	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	steel plates
Fill	Fair	U/S right settlement
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Good	BR
Wing Wall	Poor	U/S right has 2 walls; upper wall concrete, lower wall treated timbers with tiebacks, tiebacks are rotting and wall leaning out slightly

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	Good	concrete no posts
Posted Load Rating	68	
Road Surface	Fair	

DECK

Span 1

Concrete Deck	Fair	minor surface damage
---------------	------	----------------------



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 4
Date Printed: 2013/12/19
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2196	Site #:	CK-2196	Road Name:	NAHATLATCH	Inspection Date:	2013/10/01
Curb Rail/Blocks/Posts	Good	treated blocks and risers					
Deck Joints	Fair	minor cracking					
Grout Pockets	Fair						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Overall Deck Condition	Fair						
Running Surface	Fair						
Span 2							
Concrete Deck	Fair	minor surface damage					
Curb Rail/Blocks/Posts	Good						
Deck Joints	Fair	minor cracking					
Grout Pockets	Fair						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Overall Deck Condition	Fair						
Running Surface	Fair	sediment on deck					
Span 3							
Concrete Deck	Fair	minor surface damage					
Curb Rail/Blocks/Posts	Good						
Deck Joints	Fair	some cracking					
Grout Pockets	Fair						
Hardware	Fair						
Hand Rails/Walkouts	Not Applicable						
Overall Deck Condition	Fair						
Running Surface	Fair	sediment on deck					
PIERS							
Pier 1							
Bearings	Fair						
Bracing or Sheathing	Fair	bolted					
Caps	Fair	Steel H cap					
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Fair						
Overall	Fair						
Piles or Posts	Fair	H beams					
Corporate Bridge Register (CBR)							



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 4

Date Printed: 2013/12/19

User Id: IDIR\TYSMILLE

Database: PROD

Report Id: CBR001A

Structure #:	CK-2196	Site #:	CK-2196	Road Name:	NAHATLATCH	Inspection Date:	2013/10/01
Riprap	Not Applicable						
Wall	Not Applicable						
Pier 2							
Bearings	Fair						
Bracing or Sheathing	Not Applicable						
Caps	Fair			rubber pads			
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Fair						
Overall	Fair						
Piles or Posts	Fair			concrete CIP			
Riprap	Not Applicable			on BR			
Wall	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Fair			bolted and rusting			
Diaphragms	Fair			3x, bolted and rusting			
Girders	Fair			2 steel I-beams, rusting			
Hardware	Fair						
Under Trussing	Not Applicable						
Span 2							
Bracing	Fair			bolted			
Diaphragms	Fair			bolted			
Girders	Fair			2 steel I beams, rusting			
Hardware	Fair						
Under Trussing	Not Applicable						
Span 3							
Bracing	Fair			painted and bolted			
Diaphragms	Fair			painted and bolted			
Girders	Fair			2 steel I beams with surface rust and painted at pier			
Hardware	Fair						
Under Trussing	Not Applicable						



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 4 of 4
Date Printed: 2013/12/19
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2196	Site #:	CK-2196	Road Name:	NAHATLATCH	Inspection Date:	2013/10/01				
CHANNEL	Estimated Present Water Level Depth:		3.0		Estimated Present Water Level Width:		10.0				
	Estimated High Water Level Clearance:		10.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
MONITORS	#	Description									
	1	cracks in deck joints									
	2	rusting steel									
	3	lower wingwall at upstream right side									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/11/15	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):				2027	Replacement Date for light vehicle traffic (year):					
	Current Load Rating GVW (tonnes):		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:		L75		
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
	PEng Reviewer's Comment:		Monitor steel corrosion, the deck joints and the wingwall on the town upstream right side for further settlement. Settlement of timber wingwall does not appear any different then what was evident in the 2010 photos. Present load rating of L75 or 68 tonnes to continue.								
	District Staff Comment:										

Handwritten signature

Dec 19/2013



















