



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 2
Date Printed: 2013/11/22
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2241	Site #:	CK-2241	Road Name:	SPUZZUM CREEK	Inspection Date:	2013/10/29
KM:	25.40	User km:	25.40	Crossing Name:	not known	Next Inspection Date:	2016/10/29
Project File ID #:	8128	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Superstructure	Compo Girders			Abutments (Left/Right):	Steel Pipe and Precast Pad		
Total Length (metres):	18.2	# Spans:	1	Span Length(s) (metres):	17.6		
UTM Zone:	10	UTM Easting:	594416	UTM Northing:	5510294		
Inspector Name:	T. Miller			Year Built:	1994		
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Jan 2011						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	steel plates and rubber pads
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	slight HC both approaches
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	Fair	logs
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1



Concrete Deck	Fair	
Curb Rail/Blocks/Posts	Fair	
Deck Joints	Fair	



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 2
Date Printed: 2013/11/22
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2241	Site #:	CK-2241	Road Name:	SPUZZUM CREEK	Inspection Date:	2013/10/29				
Grout Pockets	Fair										
Hardware	Fair										
Hand Rails/Walkouts	Not Applicable										
Overall Deck Condition	Fair										
Running Surface	Fair	sediment on deck									
SUPERSTRUCTURE											
Span 1											
Bracing	Good	1 bay, welded									
Hardware	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		4.0				
	Estimated High Water Level Clearance:		2.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	Medium	\$1.00	brush approaches						
	2	Recommended	Medium	\$1.00	Post bridge ahead signs						
MONITORS	#	Description									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/11/22	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):			2039	Replacement Date for light vehicle traffic (year):			2039			
	Current Load Rating GVW (tonnes):		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:		L60		
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
	PEng Reviewer's Comment:		Post bridge ahead signs and brush approaches. Present load rating of L60 or 54 tonnes to continue.								
District Staff Comment:											
											
Corporate Bridge Register (CBR)											

