



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/09/04
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2279	Site #:	CK-2279	Road Name:	SUMALLO RIVER	Inspection Date:	2013/08/28
KM:	4.70	User km:	4.70	Crossing Name:	Tearse Creek (structure #11)	Next Inspection Date:	2015/08/28
Project File ID #:	7510	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right):	Crib, Log or Untreated Timber		
Total Length (metres):	14.3	# Spans:	1	Span Length(s) (metres):	13.9		
UTM Zone:	10	UTM Easting:	628669	UTM Northing:	5454552		
Inspector Name:	T. Miller			Year Built:	1992		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	creosoted timbers
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	single log sill
Fill	Fair	
Hardware	Not Applicable	
Log/Timber Cribs	Unrated	not applicable
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	0	
Delineator Missing Right	0	
Fender Condition	Fair	
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
------------------------	------	--



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/09/04
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2279	Site #:	CK-2279	Road Name:	SUMALLO RIVER	Inspection Date:	2013/08/28				
Deck to Girder Bolts	Good										
Hardware	Good										
Hand Rails/Walkouts	Not Applicable										
Nails	Good										
Overall Deck Condition	Good										
Running Planks	Good										
Sub Deck	Good										
Ties	Good	treated									
SUPERSTRUCTURE											
Span 1											
Bracing	Fair										
Diaphragms	Fair	4 bays - welded									
Girders	Fair	2 steel I-beams									
Hardware	Not Applicable										
Under Trussing	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.4		Estimated Present Water Level Width:		0.3				
	Estimated High Water Level Clearance:		3.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	Medium	\$1.00	post bridge ahead signs						
MONITORS	#	Description									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/09/04	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):				2012	Replacement Date for light vehicle traffic (year):					
	Current Load Rating GVW (tonnes):		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:		L60		
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
Corporate Bridge Register (CBR)											



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/09/04
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2279	Site #:	CK-2279	Road Name:	SUMALLO RIVER	Inspection Date:	2013/08/28
PEng Reviewer's Comment:	Post bridge ahead signs. Present load rating of L60 or 54 tonnes to continue.						
District Staff Comment:							

*Full
Sept 4/2013*







