



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/08/30
User Id: IDIRITYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2289	Site #:	CK-2289	Road Name:	UZTLIUS CREEK	Inspection Date:	2013/08/20
KM:	8.70	User km:	8.70	Crossing Name:	not known	Next Inspection Date:	2016/08/20
Project File ID #:	7972	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right):	Steel Pipe and Precast Pad		
Total Length (metres):	16.7	# Spans:	1	Span Length(s) (metres):	0		
UTM Zone:	10	UTM Easting:	617978	UTM Northing:	5522413		
Inspector Name:	T. Miller			Year Built:	1999		
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Feb 2011						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	steel plates and rubber pads
Fill	Fair	eroding downstream right bank
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	eroded downstream right bank
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	0	
Delineator Missing Right	1	
Fender Condition	Fair	logs
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1

Concrete Deck	Fair	
Curb Rail/Blocks/Posts	Poor	rotting risers and blocks
Deck Joints	Fair	



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/08/30
User Id: IDIRTYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2289	Site #:	CK-2289	Road Name:	UZTLIUS CREEK	Inspection Date:	2013/08/20				
Grout Pockets	Fair										
Hardware	Poor	loose rail bolts									
Hand Rails/Walkouts	Not Applicable										
Overall Deck Condition	Poor	due to rail									
Running Surface	Fair	sediment on deck									
SUPERSTRUCTURE											
Span 1											
Bracing	Good	bolted									
Diaphragms	Good	4 bays, bolted									
Girders	Good	2 steel I-beams									
Hardware	Good										
Under Trussing	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		3.0				
	Estimated High Water Level Clearance:		3.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	High	\$1.00	replace guardrail, risers and blocks						
	2	Recommended	Medium	\$1.00	post bridge ahead signs and missing delineator						
MONITORS	#	Description									
	1	downstream right bank erosion									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/08/30		P. Eng Reviewer Name:		Tyson Miller	
	Replacement Date for full log haul traffic (year):			2044		Replacement Date for light vehicle traffic (year):			2044		
	Current Load Rating GVW (tonnes):		68		Design Load GVW (tonnes):		68		Design Vehicle Config.:		L75
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
	PEng Reviewer's Comment:		Replace guardrail, risers and blocks. Post bridge ahead signs and replace missing delineator. Monitor downstream right bank erosion. Present load rating of L75 or 68 tonnes to continue.								
Corporate Bridge Register (CBR)											



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/08/30
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2289	Site #:	CK-2289	Road Name:	UZTLIUS CREEK	Inspection Date:	2013/08/20
District Staff Comment:							

Fill
Aug 30 / 2013





