



BC Ministry of
Forests and Range

Page 1 of 1

Corporate Bridge Register (CBR) SITE INVENTORY DATA FORM

*Site # CK-2335		*Site Status ☒ Active ☐ Barricaded/Closed ☐ Deactivated/Closed ☐ Proposed ☐ Transferred ☐ Under Construction	
*Site Type: ☒ Crossing ☐ Storage			
*Project File ID#: 8013		*Br. 01	
*Forest District: CHILWICK			
Management Area:			
*Forest Service Road: STAVE			
*Kilometres: 7.2		User Kilometres:	
*Crossing Name: SIDE CRK		Close Proximity ☐ Yes ☐ No Inspection Required?	
*Inspection Status: ☐ Inspect ☐ Do Not Inspect			
*BCTS Business Area (if applicable):			
Trim Map Sheet #:		1:50,000 Map Sheet #:	
Special Access Requirements: ☐ ATV ☐ Boat ☐ 4-Wheel Drive ☐ Gate Key ☒ Helicopter ☐ Isolated Public Access		Special Equipment Requirements: ☐ Peeper Truck ☐ Scuba	
Point of Access Description:			
Coordinates Longitude: (ddd / mm / ss.s)		Latitude: (ddd / mm / ss.s)	
UTM Zone: 10	UTM Easting: 556372	UTM Northing: 5480654	

*Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "CULVERTS"

GENERAL	
*Structure #: CK-2335	*Site #: CK-2335
*Type/Class: ☒ Major Culvert ☐ Woodbox/Log Culvert	Crossing Name:
*Forest District: Chilliwack	Management Area:
*Forest Service Road: Stave	Kilometres: 7.2
*Project File ID#: 8013	*Br. 01
Built For: ☐ BC Timber Sales ☐ Other Commercial Users ☐ Road Use Permit Holder ☐ Operations Division ☐ Road Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: Non-Status Road ☐ Inherited: Reallocation ☒ New Structure ☐ Replacement Structure ☐ Inherited: From Oil & Gas/ Other Ministry ☐ Inherited: Transfers from Other Ministries	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): <small>(PEng to enter / update this value on structure details screen in CBR)</small>	Design Load Rating GVW (tonnes): <small>(Typically obtained from design drawings)</small>
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
Portable Structure? ☐ Yes ☐ No	
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): <small>(PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).</small> <div style="text-align: center; font-size: 1.5em;">2015</div>
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR)
Structure Inventory Data Form
"CULVERTS"

STRUCTURAL DETAILS

*Culvert Number: 1 of 1

*Culvert Length (metres):

12.5

Gradient:

*Culvert Type (not required for woodbox/log):

- ☐ Box ☒ Elliptical
☐ Open Bottom ☐ Round

*Culvert Material:

- ☐ Concrete ☒ Corrugated Steel
☐ Log ☐ Other
☐ Steel Non-Corrugated

Inlet Cover Depth (mm): 300

Outlet Cover Depth (mm): 400

*Opening Height (mm): 1800

*Opening Width (mm): 2300

Headwall Location:

- ☐ Both ☐ Inlet
☐ None ☐ Outlet

Open Bottom Substructure (not required for woodbox/log culvert):

- ☐ Cast in Place Concrete Footing
☐ Lock-Block Footing
☐ Piles
☐ Precast Concrete Footing
☐ Steel Footing

Comments:



BC Ministry of Forests and Range
Routine Condition Culvert Inspection Form

GENERAL INFORMATION

(enter either long/lat or UTM below- not both)

*Site #:

CK-2335

*Crossing Name:

Side Creek

*Type/Class:

☒ Major Culvert

☐ Woodbox/Log Culvert

*Project File ID#

8013

*Structure #:

CK-2335

*FSR Name:

Stave River

*Forest District:

Chilliwack

*Kilometres:

7.20

*Br.

0

User km:

7.20

Longitude: (ddd / mm / ss.s)

Latitude: (ddd / mm / ss.s)

OR

UTM Zone

10

UTM Easting

556372

UTM Northing

5480654

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G F P UR	
Bridge Ahead Signs Missing	0 1 2	But not narrowed
Brushing Required	Yes No	But not narrowed
Delineator Missing Left	0 1 2	But not narrowed
Delineator Missing Right	0 1 2	But not narrowed
Fender Condition	E G F P None UR	
Posted Load Rating	(tonnes) or None	
Road Surface	E G F P UR	

GENERAL CULVERT ITEMS

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Baffles (N/A to woodbox/log culvert)	E G F P N/A UR	
Bolted Connections (N/A to woodbox/log culvert)	E G F P N/A UR	
Coupled Connections (N/A to woodbox/log culvert)	E G F P N/A UR	
Coating (N/A to woodbox/log culvert)	E G F P N/A UR	Heavy rust on floor
Embedment Materials (N/A to woodbox/log culvert)	E G F P N/A UR	
Fill	E G F P UR	
Roof	E G F P UR	
Side Walls	E G F P UR	
Floor	E G F P N/A UR	Heavy rust
Head Walls	E G F P N/A UR	
Wing Walls	E G F P N/A UR	
Inlet	E G F P UR	
Outlet	E G F P UR	
Overall	E G F P UR	
Riprap	E G F P N/A UR	
Trash Rack	E G F P N/A UR	
Weirs/Backwater Structures	E G F P N/A UR	
Footing (N/A to woodbox/log culvert)	E G F P N/A UR	

LOG CULVERTS ONLY

Stringer #	Stringer Rot Depth (mm)	Diameter (mm)	Stringer Species	Comments (a comment is mandatory if condition "Poor" is selected)
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				



Routine Condition Culvert Inspection Form

GENERAL INFORMATION

*Site #: CK-2335

*Structure #: CK2335

LOG CULVERTS ONLY (continued)

Stringer #	Stringer Rot Depth (mm)	Diameter (mm)	Stringer Species	Comments (a comment is mandatory if condition "Poor" is selected)
13				
14				
15				
16				
17				
18				
19				
20				
21				

Comments

Stream CHANNEL

*Est. Present Water Level Depth 0.05 (m) *Est. Present Water Level Width 1 (m) *Est. High Water Level Clearance 1.2 (m)

HAZARDS (circle yes or no for each item)

High Water? Yes No Scour? Yes No Ice? Yes No Debris? Yes No Aggradation? Yes No

Comments

REPAIRS:

☐ Recommended☒ Not required (H = High, M = Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		
2	H M L		
3	H M L		

*Monitoring Status:

☐ Recommended☒ Not required

Monitor Item #	*Monitor Description
1	
2	


PHOTO LOG

Photo #	Description	Photo #	Description
1	Inlet	5	Inside
2	From Left		
3	Outlet		
4	From Right		

INSPECTOR TO COMPLETE THIS SECTION


As-built Drawings Checked? Yes ☒ No	P Eng Inspection Required? Yes ☒ No	Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): 2015 (PEng to review and evaluate inspector's estimate of Log Haul Traffic Replacement (year) on structure details screen in CBR as necessary)
*Date of Inspection (yyyy/mm/dd) 2013/09/25	*Inspection Company Name ONSITE	*Inspector's Name (print) Bromy Araki
Inspector's Comments		Inspector's Signature 

PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION

Current Load Rating GVW (tonnes): 68 tonnes (PEng to update structure details screen in CBR as necessary)	Date of Next Planned Inspection (yyyy/mm/dd) 2016/09/30
Reviewer Company Name MoF	Reviewed by - PEng's Name (print) T. Miller
Reviewed by - PEng's Signature 	Date Reviewed (yyyy/mm/dd) 2014/01/14

PEng Reviewer's Comments
Present load rating of L75 or 68 tonnes to continue.

* Denotes Mandatory Information for Corporate Bridge Register





CK-2335 Inlet



CK-2335 From Left



CK-2335 Outlet



CK-2335 From Right



CK-2335 Inside

25-Sep-13