



BC Ministry of
Forests and Range

Page 1 of 1

Corporate Bridge Register (CBR) SITE INVENTORY DATA FORM

*Site # CK-2336		*Site Status ☒ Active ☐ Barricaded/Closed ☐ Deactivated/Closed ☐ Proposed ☐ Transferred ☐ Under Construction	
*Site Type: ☒ Crossing ☐ Storage			
*Project File ID#: 8013		*Br. 61	
*Forest District: CHILLIWACK			
Management Area:			
*Forest Service Road: STAVE			
*Kilometres: 7.2		User Kilometres:	
*Crossing Name: SIDE CRK		Close Proximity Inspection Required? ☐ Yes ☐ No	
*Inspection Status: ☐ Inspect ☐ Do Not Inspect			
*BCTS Business Area (if applicable):			
Trim Map Sheet #:		1:50,000 Map Sheet #:	
Special Access Requirements: ☐ ATV ☐ Boat ☐ 4-Wheel Drive ☐ Gate Key ☒ Helicopter ☐ Isolated Public Access		Special Equipment Requirements: ☐ Peeper Truck ☐ Scuba	
Point of Access Description:			
Coordinates Longitude: (ddd / mm / ss.s)		Latitude: (ddd / mm / ss.s)	
UTM Zone: 10	UTM Easting: 556345	UTM Northing: 5480564	

*Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "CULVERTS"

GENERAL	
*Structure #: CK-2336	*Site #: CK-2336
*Type/Class: ☒ Major Culvert ☐ Woodbox/Log Culvert	Crossing Name: SIDE CRK
*Forest District: CHILLIWACK	Management Area:
*Forest Service Road: STAVE	Kilometres: 7.2
*Project File ID#: 8013	*Br. 01
Built For: ☐ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ ☐ Inherited: Non-Status Road Other Ministry ☐ Inherited: Reallocation ☐ Inherited: Transfers from ☒ New Structure Other Ministries ☐ Replacement Structure	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): (PEng to enter / update this value on structure details screen in CBR)	Design Load Rating GVW (tonnes): (Typically obtained from design drawings)
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
Portable Structure? ☐ Yes ☐ No	
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): (PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR). 2045
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR)
Structure Inventory Data Form
"CULVERTS"

STRUCTURAL DETAILS		
*Culvert Number: <u>1</u> of 1	*Culvert Length (metres): <u>12.5</u>	Gradient: <u>2.0 %</u>
*Culvert Type (not required for woodbox/log): ☐ Box ☒ Elliptical ☐ Open Bottom ☐ Round		*Culvert Material: ☐ Concrete ☒ Corrugated Steel ☐ Log ☐ Other ☐ Steel Non-Corrugated)
Inlet Cover Depth (mm): <u>450</u>	Outlet Cover Depth (mm): <u>800</u>	
*Opening Height (mm): <u>1800</u>	*Opening Width (mm): <u>2300</u>	
Headwall Location: ☐ Both ☐ Inlet ☐ None ☐ Outlet		Open Bottom Substructure (not required for woodbox/log culvert): ☐ Cast in Place Concrete Footing ☐ Lock-Block Footing ☐ Piles ☐ Precast Concrete Footing ☐ Steel Footing
Comments:		



BC Ministry of Forests and Range
Routine Condition Culvert Inspection Form

Page 1 of 2


GENERAL INFORMATION				(enter either long/lat or UTM below – not both)		
*Site #: CK-2336	*Crossing Name: Gold Creek	*Type/Class: ☒ Major Culvert ☐ Woodbox/Log Culvert	*Project File ID# 8613			
*Structure #: CK-2336			*Br. 01			
*FSR Name: Stave River	*Forest District: Chilliwack	*Kilometres: 7.20	User km: 7.20			
Longitude: (ddd / mm / ss.s)		OR	UTM Zone: 10	UTM Easting: 556345	UTM Northing: 5480564	
Latitude: (ddd / mm / ss.s)						
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated						
Item	Present Condition (circle or fill-in)					Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E	G	F	P	UR	
Bridge Ahead Signs Missing	0	1	2	But not narrowed		
Brushing Required	Yes	No				
Delineator Missing Left	0	1	2	But not narrowed		
Delineator Missing Right	0	1	2	But not narrowed		
Fender Condition	E	G	F	P	None	UR
Posted Load Rating	(tonnes) or None					
Road Surface	E	G	F	P	UR	
GENERAL CULVERT ITEMS						
Item	Present Condition (circle)					Comments (a comment is mandatory if condition "Poor" is selected)
Baffles (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
Bolted Connections (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
Coupled Connections (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
Coating (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
Embedment Materials (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
Fill	E	G	F	P	UR	
Roof	E	G	F	P	UR	
Side Walls	E	G	F	P	UR	
Floor	E	G	F	P	N/A	UR
Head Walls	E	G	F	P	N/A	UR
Wing Walls	E	G	F	P	N/A	UR
Inlet	E	G	F	P	UR	
Outlet	E	G	F	P	UR	
Overall	E	G	F	P	UR	
Riprap	E	G	F	P	N/A	UR
Trash Rack	E	G	F	P	N/A	UR
Weirs/Backwater Structures	E	G	F	P	N/A	UR
Footings (N/A to woodbox/log culvert)	E	G	F	P	N/A	UR
LOG CULVERTS ONLY						
Stringer #	Stringer Rot Depth (mm)	Diameter (mm)	Stringer Species	Comments (a comment is mandatory if condition "Poor" is selected)		
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						



Routine Condition Culvert Inspection Form

GENERAL INFORMATION				
*Site #: CK-2330		*Structure #: CK-2336		
LOG CULVERTS ONLY (continued)				
Stringer #	Stringer Rot Depth (mm)	Diameter (mm)	Stringer Species	Comments (a comment is mandatory if condition "Poor" is selected)
13				
14				
15				
16				
17				
18				
19				
20				
21				
Comments				
Stream CHANNEL				
*Est. Present Water Level Depth 0.0 (m)		*Est. Present Water Level Width 0.0 (m)		*Est. High Water Level Clearance 1.2 (m)
HAZARDS (circle yes or no for each item)				
High Water?	Yes No	Scour?	Yes No	Ice? Yes No
Debris?	Yes No	Aggradation?	Yes No	
Comments				
REPAIRS: ☐ Recommended ☒ Not required (H = High, M = Medium, L = Low)				
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description	
1	H M L			
2	H M L			
3	H M L			
*Monitoring Status: ☐ Recommended ☒ Not required				
Monitor Item #	*Monitor Description			
1				
2				
PHOTO LOG				
Photo #	Description	Photo #	Description	
1	Inlet	5	Outlet	
2	From left			
3	Inside			
4	From right			
INSPECTOR TO COMPLETE THIS SECTION				
As-built Drawings Checked? Yes No		P Eng Inspection Required? Yes No		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): (PEng to review and evaluate inspector's estimate, and determine Full Log Haul Traffic Replacement (year) on structure details screen if CBR is necessary.)
*Date of Inspection (yyyy/mm/dd) 2013/09/25	*Inspection Company Name ONSITE	*Inspector's Name (print) Jeremy Araki	Inspector's Signature J. C. P. ARAKI # 29755 PROFESSIONAL BRITISH COLUMBIA ENGINEER	
PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION				
Current Load Rating GVW (tonnes): 68 tonnes (PEng to update structure details screen in CBR as necessary)		Date of Next Planned Inspection (yyyy/mm/dd) 2016/09/30		
Reviewer Company Name MoF	Reviewed by - PEng's Name (print) T. Miller	Reviewed by - PEng's Signature	Date Reviewed (yyyy/mm/dd) 2014/01/14	
PEng Reviewer's Comments Present load rating of L75 or 68 tonnes to continue.				

* Denotes Mandatory Information for Corporate Bridge Register






CK-2336 Inlet



CK-2336 From Left



CK-2336 Inside



CK-2336 From Right



CK-2336 Outlet

25-Sep-13