



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2348	Site #:	CK-2348	Road Name:	COGBURN CREEK	Inspection Date:	2013/10/31
KM:	4.80	User km:	4.80	Crossing Name:	(No Creek Present)	Next Inspection Date:	2016/10/31
Project File ID #:	5748	Br.	02	Forest District:	Chilliwack Forest District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right):	Steel Pipe and Precast Pad		
Total Length (metres):	24.4	# Spans:	1	Span Length(s) (metres):	0		
UTM Zone:	10	UTM Easting:	592044	UTM Northing:	5490020		
Inspector Name:	T. Miller			Year Built:	1997		
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Feb 2011						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	concrete
Corrosion Protection	Good	
Caps or Sills	Good	steel plates and rubber pads
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Fair	pipe risers on exposed spread footings
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	1	
Delineator Missing Right	1	
Fender Condition	Fair	logs
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1

Concrete Deck	Fair	composite, flared D/S
Curb Rail/Blocks/Posts	Poor	rotten
Deck Joints	Fair	minor cracks



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2348	Site #:	CK-2348	Road Name:	COGBURN CREEK	Inspection Date:	2013/10/31				
Grout Pockets	Fair										
Hardware	Poor	loose rail									
Hand Rails/Walkouts	Not Applicable										
Overall Deck Condition	Poor	due to rail									
Running Surface	Fair	minor surface damage and plenty of organics on deck									
SUPERSTRUCTURE											
Span 1											
Bracing	Good	bolted									
Diaphragms	Good	6 bays, bolted									
Girders	Good	2 steel I beams, spliced									
Hardware	Good										
Under Trussing	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0				
	Estimated High Water Level Clearance:		0.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:	no stream present									
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Recommended	Medium	\$1.00	replace guardrail, risers and blocks						
	2	Recommended	Medium	\$1.00	brush with activity						
	3	Recommended	Medium	\$1.00	post bridge ahead signs and replace missing delineators						
MONITORS	#	Description									
GENERAL	Professional Inspection Required?		No	Regional Review Date:		2013/11/20	P. Eng Reviewer Name:		Tyson Miller		
	Replacement Date for full log haul traffic (year):			2042	Replacement Date for light vehicle traffic (year):			2042			
	Current Load Rating GVW (tonnes):		136	Design Load GVW (tonnes):		136	Design Vehicle Config.:		L150		
	Inspector's Estimated Full Log Haul Replacement (year):										
	Inspector's Comment:										
	PEng Reviewer's Comment:		Replace guardrail, risers and sideblocks with activity. Brush, replace missing delineators and post bridge ahead signs. Present load rating of L150 or 136 tonnes to continue.								
Corporate Bridge Register (CBR)											



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A

Structure #:	CK-2348	Site #:	CK-2348	Road Name:	COGBURN CREEK	Inspection Date:	2013/10/31
District Staff Comment:							

T. W. Miller
Nov 20/2013







