

CK-2034

CHEHALIS-STATLU 9.7km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude	Longitude
49°23'10.5"	-122°6'11.7"
Road Name	CHEHALIS-STATLU
User km	9.7
Current Load Rating (tonnes)	
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	7
Deck Width (m)	9999

Updated Data

Latitude	Longitude
49°23'10.46"	-122°6'11.32"
HD Diff. (m)	7.7
Accuracy (m)	5
Chehalis-Statlu	
9.4	
NA	
N	
Others	
Gravel	
Other	
Other	
0	
5.0	

Inspection

Date of Inspection 2014-10-10 11:28:41 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Structure is now a ford and site does not warrant a structure inspection. Inspect with regular road inspections.



T. Miller
Dec 15/2014

CK-2034

CHEHALIS-STATLU 9.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2 NA

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2 NA

Fender Condition NA

Posted Load Rating NA

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

CK-2034

CHEHALIS-STATLU 9.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 0

Ice ☐

Comments log stringers have been removed and crossing is a ford

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1

2

3

Sketch
(Select Signature)

CK-2034

CHEHALIS-STATLU 9.7km

2014 Inspection



Approach from Left Bank when facing downstream



looking downstream



looking upstream



Approach from Right Bank when facing downstream