

CK-2048

CHILLIWACK RIVER 1km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude Longitude
49°5'33.29" -121°26'32.5"

Road Name CHILLIWACK RIVER
User km 1
Current Load Rating (tonnes) 54
Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2300

Opening Width (mm) 2300

Inlet Cover (mm) 800

Outlet Cover (mm) 800

Culvert Gradient %

Culvert Length (m) 14.5

Deck Width (m)

Updated Data

Latitude Longitude
49°5'33.21" -121°26'32.16"

HD Diff. (m) 7.3 Accuracy (m) 10

Chilliwack Lake

0.9

L60 or 54 tonnes

Major Culvert

Round

Corrugated Steel

2300

2300

900

900

5

14.5

7.0

Inspection

Date of Inspection 2014-10-31 12:52:53 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Present load rating of L60 or 54 tonnes to continue.

T. Miller
Dec 17/2014



CK-2048

CHILLIWACK RIVER 1km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition NA

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

CK-2048

CHILLIWACK RIVER 1km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection

Culvert

Baffles N/A

Bolted Connections Good

Coating Good

Coupled Connections N/A

Embedment Materials N/A

Fill Good

Floor Good

Footing Fair

Head Walls N/A

Inlet Fair

Outlet Fair 2m drop

Overall Fair

Rip Rap Fair

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

CK-2048

CHILLIWACK RIVER 1km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.3

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 2.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 1.0

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1

2

3

Sketch
(Select Signature)

CK-2048

CHILLIWACK RIVER 1km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Outlet



Inlet