

CK-2112

HARRISON EAST 51.7km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude	Longitude
49°43'34.79"	-121°51'10.8"
Road Name	HARRISON EAST
User km	51.7
Current Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	21.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°43'34.12"	-121°51'11.27"
HD Diff. (m)	22.9
Accuracy (m)	5
Harrison East	
50.5	
L150 or 136 tonnes	
Permanent Bridge	
N	
Steel I-beam	
Concrete Composite	
Steel Pipe and Precast Pad	
Steel Pipe and Precast Pad	
1	
21.4	
4.9	

Inspection

Date of Inspection 2014-08-26 10:44:08 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Present load rating of L150 or 136 tonnes to continue.

Fill
Dec 18/2014



CK-2112

HARRISON EAST 51.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair no fender upstream right approach

Posted Load Rating 136

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Fair left upstream pad has been casted below to help from erosion - appears to be holding up well

Caps or Sills Good steel plates and rubber pads

Piles or Posts Good

Ballast Wall Good

Wing Wall Good only right approach

Bracing N/A none due to the short post height

Hardware N/A

Fill Fair

Riprap Good

Bearings Good

CK-2112

HARRISON EAST 51.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection Good

Deck

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

CK-2112

HARRISON EAST 51.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Steel/Concrete

Girders Good 2 steel I beams

Diaphragms Good 4 - bolted

Bracing N/A

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Comment
--------------------	---------	--------	------------------	-------------------	---------

CK-2112

HARRISON EAST 51.7km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.2

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 2.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 3.0

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1

2

3

Sketch
(Select Signature)

CK-2112

HARRISON EAST 51.7km

2014 Inspection



Approach from Left Bank when facing downstream



Deck



looking upstream



Approach from Right Bank when facing downstream

CK-2112

HARRISON EAST 51.7km

2014 Inspection



Left Bank Abutment when facing downstream



left upstream pad



left upstream pad



Right Bank Abutment when facing downstream

CK-2112

HARRISON EAST 51.7km

2014 Inspection



superstructure