

CK-2117

COGBURN CREEK 3.4km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude	Longitude
49°33'27.6"	-121°44'24.6"
Road Name	COGBURN CREEK
User km	3.4
Current Load Rating (tonnes)	0
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	11.9
Deck Width (m)	5.5

Updated Data

Latitude	Longitude		
49°33'27.7"	-121°44'28.23"		
HD Diff. (m)	72.9	Accuracy (m)	5
Cogburn Creek			
0 tonnes			
Permanent Bridge			
N			
Steel I-beam			
Concrete Composite			
Concrete Cast in Place			
Concrete Cast in Place			
1			
11.9			
5.5			

Inspection

Date of Inspection 2014-08-28 11:28:55 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

0 tonnes load rating. Replace with activity.

Dec 17/2014



CK-2117

COGBURN CREEK 3.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Fair

tight HC both approaches

Bridge Ahead Signs
Missing☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left☐ 0 ☐ 1 ☒ 2Delineator Missing
Right☐ 0 ☒ 1 ☐ 2

Fender Condition Poor

missing

Posted Load Rating

posted at 0km of Cogburn Creek FSR

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Poor

leaning, fractured

Caps or Sills Poor

right bearing column is sloped into stream and steel does not bearing completely on concrete columns

Piles or Posts N/A

Ballast Wall Poor

rotten logs

Wing Wall Poor

rotten

Bracing N/A

Hardware N/A

Fill Poor

failing

Riprap Poor

scoured

Bearings Poor

not bearing completely

CK-2117

COGBURN CREEK 3.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection N/A

Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Poor rotten

Hand Rails/Walkouts N/A

Hardware Poor loose rail bolts

Overall Deck Condition Poor due to rail

Gravel Depth (mm)

CK-2117

COGBURN CREEK 3.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Steel/Concrete

Girders Poor old riveted steel girders with different dimensions

Diaphragms Fair

Bracing Fair

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Comment

CK-2117

COGBURN CREEK 3.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.5

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 5.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 3.0

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	replace entire structure with activity
---	--------	--

2		
---	--	--

3		
---	--	--

Monitor Item

Monitor Description

Monitoring Frequency

1	for failure	
---	-------------	--

Anually

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)

CK-2117

COGBURN CREEK 3.4km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Upstream Profile

CK-2117

COGBURN CREEK 3.4km

2014 Inspection



upstream right wing wall



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream Profile