

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude	Longitude
49°19'42.7"	-121°32'39.5"
Road Name	LORENZETTA HUNTER
User km	4.9
Current Load Rating (tonnes)	5
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	21.4
Deck Width (m)	4.2

Updated Data

Latitude	Longitude		
49°19'42.34"	-121°32'39.65"		
HD Diff. (m)	11.6	Accuracy (m)	5
Lorenzetta Hunter			
4.7			
L75 or 68 tonnes			
Permanent Bridge			
N			
Steel I-beam			
Timber – Treated			
Concrete Lock Blocks			
Concrete Cast in Place			
1			
21.4			
4.3			

Inspection

Date of Inspection 2014-09-22 12:19:55 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Post bridge ahead signs and monitor deck. If any movement is noticed then recommend placing deck clips on remaining ties with risers attached to fasten deck. L75 or 68 tonnes load rating.



T. Miller
Dec 19/2014

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Fair lock blocks left bank, CIP right bank

Caps or Sills Fair

Piles or Posts N/A

Ballast Wall Fair treated timbers

Wing Wall Fair only on right bank - CIP

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection N/A

Deck

Running Surface N/A

Running Planks Good

Sub Deck Good treated

Ties Good treated

Nails Good

Deck to Girder Bolts Fair about 30% missing as holes in girders don't align with ties - originally designed for a modular deck and permanent deck installed - watched 2 loaded trucks go over and absolutely no movement of deck

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good steel risers

Hand Rails/Walkouts N/A

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection

CBR iPad Offline Ver 0.17

Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Comment

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.5

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 7.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 5.0

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	post bridge ahead signs
---	--------	-------------------------

2		
---	--	--

3		
---	--	--

Monitor Item

Monitor Description

Monitoring Frequency

1	deck for movement
---	-------------------

Routine Inspection

2	
---	--

3	
---	--

Sketch
(Select Signature)

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



guardrail connection

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection



guardrail connection 2



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



upstream left approach fender

CK-2158

LORENZETTA HUNTER 4.9km

2014 Inspection



Right Bank Abutment when facing downstream



left bank bearing



superstructure