

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection

CBR iPad Offline Ver 0.15

CBR Data

Latitude	Longitude
49°53'9.7"	-121°42'51"
Road Name	KOOKIPI CREEK
User km	15.8
Current Load Rating (tonnes)	91
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Treated
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	24.4
Deck Width (m)	4.4

Updated Data

Latitude	Longitude		
49°53'9.9"	-121°42'50.76"		
HD Diff. (m)	7.9	Accuracy (m)	5
Kookipi Creek			
15.8			
L100 or 91 tonnes			
Permanent Bridge			
N			
Steel I-beam			
Timber – Treated			
Steel Pipe and Precast Pad			
Steel Pipe and Precast Pad			
1			
24.4			
4.3			

Inspection

Date of Inspection 2014-07-09 11:49:52 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

Replace running planks and guardrail system prior to industrial activity. Brush approaches, replace missing bridge ahead signs and delineators. Present load rating of L100 or 91 tonnes to continue.

P.Eng Comments

Replace running planks and guardrail system prior to activity. Brush approaches and replace missing bridge ahead signs and delineators. Present load rating of L100 or 91 tonnes to continue.



Handwritten signature and date: Aug 6/2014

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection

CBR iPad Offline Ver 0.15

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good steel plates and rubber pads

Piles or Posts Good

Ballast Wall Fair treated timbers, material ravelling underneath

Wing WallBracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Bearings Good

Corrosion Protection Good

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection

CBR iPad Offline Ver 0.15

Deck

Running Surface	N/A	
Running Planks	Fair	fair to poor - replace with industrial activity
Sub Deck	Fair	treated
Ties	Good	treated
Nails	Fair	
Deck to Girder Bolts	Good	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	replace with industrial activity
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose rail bolts
Overall Deck Condition	Poor	due to rotting rails
Gravel Depth (mm)		

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection

CBR iPad Offline Ver 0.15

Steel/Concrete

Girders Fair steel beams, spliced and cantilevered from bearing

Diaphragms Fair 6 - welded

Bracing Fair

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Comment

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection

CBR iPad Offline Ver 0.15

Hazards

Estimated Present Water Level Depth (m) 1.0

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 8.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 3.0

Ice ☐Comment
~**Repairs and Monitoring**

Repair Item	Priority	Repair Description
1	Medium	replace running planks and guardrail with activity
2	Medium	brush approaches
3	Medium	post bridge ahead and missing delineator

Monitor Item

Monitor Description

Monitoring Frequency

1

2

3

Sketch
(Select Signature)

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Right Bank Abutment when facing downstream

CK-2202

KOOKIPI CREEK 15.8km

2014 Inspection



superstructure



Left Bank Abutment when facing downstream