

CK-2334

STAVE RIVER 4.4km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude Longitude
49°27'21.39" -122°13'3.9"

Road Name STAVE RIVER
User km 4.4
Current Load Rating (tonnes) 68
Structure Class Major Culvert
Culvert Type Elliptical
Culvert Material Corrugated Steel

Opening Height (mm) 3330
Opening Width (mm) 5200
Inlet Cover (mm) 600
Outlet Cover (mm) 500
Culvert Gradient % 2
Culvert Length (m) 18
Deck Width (m)

Updated Data

Latitude Longitude
49°27'21.34" -122°13'4.74"
HD Diff. (m) 17.0 Accuracy (m) 5

Stave River
4.4
L75 or 68 tonnes
Major Culvert
Elliptical
Corrugated Steel

Multiplate Pipe Arch:
5050 x 3330

Round:
2200

500
1.0
5
20
7.5

Inspection

Date of Inspection 2014-12-02 1:09:09 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Present load rating of L75 or 68 tonnes to continue.



CK-2334

STAVE RIVER 4.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition NA

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

CK-2334

STAVE RIVER 4.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection

Culvert

Baffles N/A

Bolted Connections Good

Coating Fair

Coupled Connections Good just for round CSP

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Fair

Outlet Fair

Overall Fair

Rip Rap Fair

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

CK-2334

STAVE RIVER 4.4km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.2

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 2.0

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 2.5

Ice ☐

Comments secondary culvert is 2200mm round corrugated steel

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1

2

3

Sketch
(Select Signature)

CK-2334

STAVE RIVER 4.4km

2014 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Inlet



Inlet x 2

CK-2334

STAVE RIVER 4.4km

2014 Inspection



Outlet



Outlet x 2