

CK-2448

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

CBR Data

Latitude Longitude
49°11'47.9" -122°9'36"

Road Name NORRISH CREEK
User km
Current Load
Rating (tonnes) 136
Structure Class Permanent Bridge
Portable N

Superstructure Concrete Slab Girders

Deck Type Concrete

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 12.6

Deck Width (m) 6

Updated Data

Latitude Longitude
49°11'47.96" -122°9'35.99"

HD Diff. (m) 1.8 Accuracy (m) 5

Norrish Creek

1.8

136 tonnes

Permanent Bridge

N

Concrete Slab Girders

Concrete

Steel Pipe and Precast Pad

Steel Pipe and Precast Pad

1

12.6

6

Inspection

Date of Inspection 2014-07-08 9:34:03 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

Replace the right hand delineators that are posted on left sides with proper left hand delineators. Monitor new riprap for scour and lock block settlement. Downstream guardrail will need to be replaced soon. Provide 175mm gravel surfacing over concrete slabs extending into approaches as per original design. Present load rating of L150 or 136 tonnes to continue.

P.Eng Comments

Replace the right hand delineators that are posted on the left sides with proper left hand delineators. Monitor new riprap for scour and lockblock settlement.

Downstream guardrail will need to be replaced soon. Provide 175mm gravel surfacing over the concrete slabs extending into the approaches as per the original design. Present load rating of L150 or 136 tonnes to continue.



File
July 24/2014

CK-2448

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2 both delineators on left sides are actually right hands

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 136090

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Fair concrete caps

Piles or Posts Fair not painted, 2 bays right side

Ballast Wall Fair lock blocks, differential settlement left side (no levelling pad)

Wing WallBracing Fair lockblocks downstream right side

Hardware Fair

Fill Fair

Riprap Fair recent work completed

Bearings Fair

Corrosion Protection Poor not painted

CK-2448

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair upstream is new and tight, downstream fair to poor

Hand Rails/Walkouts N/A

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2448

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Steel/Concrete

Girders Fair 7 slabs, flared downstream

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted shear connectors Fair welded

Log

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Comment

CK-2448

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Hazards

Estimated Present Water Level Depth (m) 0.3

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 4.0

Aggradation ☐Scour ☒

Estimated High Water Level Clearance (m) 2.0

Ice ☐

Comment recent riprap added to protect both abutments and downstream right wingwall

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	
---	--------	--

2	Medium	replace left hand delineators
---	--------	-------------------------------

3		
---	--	--

Monitor Item

Monitor Description

Monitoring Frequency

1	scour	
---	-------	--

Routine Inspection

2	lock block settlement	
---	-----------------------	--

Routine Inspection

3		
---	--	--

Sketch
(Select Signature)

CK-2448

NORRISH CREEK km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Upstream Profile

CK-2448

NORRISH CREEK km

2014 Inspection



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



right downstream wing wall