

CK-2451

NORRISH CREEK 5.6km

2014 Inspection

CBR iPad Offline Ver 0.15

CBR Data

Latitude	Longitude
49°13'29.6"	-122°8'41"
Road Name	NORRISH CREEK
User km	5.6
Current Load Rating (tonnes)	63
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	3000
Opening Width (mm)	3000
Inlet Cover (mm)	400
Outlet Cover (mm)	400
Culvert Gradient %	
Culvert Length (m)	11
Deck Width (m)	

Updated Data

Latitude	Longitude		
49°13'28.95"	-122°8'40.93"		
HD Diff. (m)	20.1	Accuracy (m)	5
Norrish Creek	5.7	BCL-625 or 63 tonnes	
Major Culvert	Round	Corrugated Steel	
	3000	3000	
	500	400	
	11		

Inspection

Date of Inspection 2014-07-08 10:22:32 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

The culvert has sustained damage, continue to monitor. Present load rating of BCL-625 or 63 tonnes to continue.

P.Eng Comments

The culvert has sustained damage, continue to monitor the overall shape. Present load rating of BCL-625 or 63 tonnes to continue.



J.W. Miller
July 24/2014

CK-2451

NORRISH CREEK 5.6km

2014 Inspection

CBR iPad Offline Ver 0.15

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated na

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing WallBracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2451

NORRISH CREEK 5.6km

2014 Inspection

CBR iPad Offline Ver 0.15

Culvert

Baffles	N/A	
Bolted Connections	N/A	
Coating	Fair	
Coupled Connections	N/A	
Embedment Materials	N/A	
Fill	Fair	0.4 m
Floor	Poor	damaged
Footing	Fair	
Head Walls	N/A	
Inlet	Fair	damaged but functional
Outlet	Fair	damaged but functional
Overall	Fair	
Rip Rap	Fair	
Roof	Fair	
Sidewalls	Poor	damaged
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

CK-2451

NORRISH CREEK 5.6km

2014 Inspection

CBR iPad Offline Ver 0.15

Hazards

Estimated Present Water Level Depth (m) 0.2

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 2.8

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 1.0

Ice ☐

Comment

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1 culvert shape

Routine Inspection

2

3

Sketch
(Select Signature)

CK-2451

NORRISH CREEK 5.6km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Inlet



looking through culvert

CK-2451

NORRISH CREEK 5.6km

2014 Inspection



Outlet