

CK-2452

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

CBR Data

Latitude	Longitude
49°13'58.9"	-122°8'9.9"
Road Name	NORRISH CREEK
User km	
Current Load Rating (tonnes)	150
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel Box Beam
Deck Type	Concrete
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.8

Updated Data

Latitude	Longitude		
49°13'58.83"	-122°8'9.94"		
HD Diff. (m)	2.3	Accuracy (m)	5
Norrish Creek			
7.1			
L165 or 150 tonnes			
Temporary Bridge			
N			
Steel Box Beam			
Concrete Composite			
CIP and log crib			
CIP, lockblocks and single log sill			
1			
18.3			
4.8			

Inspection

Date of Inspection 2014-07-08 10:36:41 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

Monitor left bank abutment condition and deck joints. Present load rating of L165 or 150 tonnes to continue.

P.Eng Comments

Monitor left bank abutment condition and deck joints. Present load rating of L165 or 150 tonnes to continue.



T.W. Miller
July 24/2014

CK-2452

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y minor

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 149700

Road Surface Fair

Abutment

Log/Timber Cribs Fair left bank only, on top of CIP

Tie Backs Fair

Bin Wall N/A

Concrete Fair vertical crack on left CIP

Caps or Sills Fair right bank, single log sill

Piles or Posts N/A

Ballast Wall Fair

Wing WallBracing N/A

Hardware N/A

Fill Fair

Riprap Poor none in front of either abutment

Bearings Fair

Corrosion Protection N/A

CK-2452

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Deck

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Fair	
Grout Pockets	Fair	
Deck Joints	Fair	minor cracking on some joints - monitor
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Good	w-beam with steel risers and brackets
Hand Rails/Walkouts	N/A	
Hardware	Fair	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2452

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Steel/Concrete

Girders Fair

2 steel box beams

Diaphragms Fair

2 - bolted on either end

Bracing N/A

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Comment

CK-2452

NORRISH CREEK km

2014 Inspection

CBR iPad Offline Ver 0.15

Hazards

Estimated Present Water Level Depth (m) 0.5

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 10.

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 3.0

Ice ☐Comment
~**Repairs and Monitoring**

Repair Item	Priority	Repair Description
1		
2		
3		

Monitor Item

Monitor Description

Monitoring Frequency

1	deck joints	Routine Inspection
2	left bank abutment condition	Routine Inspection
3		

Sketch
(Select Signature)

CK-2452

NORRISH CREEK km

2014 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream

CK-2452

NORRISH CREEK km

2014 Inspection



Left Bank Abutment when facing downstream