

CK-2489

BENCH 7.2km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude Longitude
49°5'.99" -121°43'27"

Road Name BENCH
User km 7.2
Current Load Rating (tonnes)
Structure Class Major Culvert
Culvert Type Open Bottom
Culvert Material Corrugated Steel
Opening Height (mm) 1910
Opening Width (mm) 3660
Inlet Cover (mm) 1800
Outlet Cover (mm) 2000
Culvert Gradient %
Culvert Length (m) 21.4
Deck Width (m)

Updated Data

Latitude Longitude
49°5'1.86" -121°43'27.16"

HD Diff. (m) 26.8 Accuracy (m) 5

Bench

7.2

L100 or 91 tonnes

Major Culvert

Open Bottom

Corrugated Steel

1910

3660

1.8

2.3

5

21.4

5.5

Inspection

Date of Inspection 2014-09-10 2:21:02 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

Present load rating of L100 or 91 tonnes to continue.

T. W. Miller
Nov 27/14



CK-2489

BENCH 7.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating **not posted**

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

CK-2489

BENCH 7.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection

Culvert

Baffles N/A

Bolted Connections Good

Coating Good

Coupled Connections N/A

Embedment Materials Fair some of the fill within the culvert has washed out but footing still in tact (wrapped in geogrid and geotextile)

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Fair

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater Structures N/A

Wing Walls N/A

CK-2489

BENCH 7.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m) 0.2

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 1.8

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 1.0

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Monitor Item

Monitor Description

Monitoring Frequency

1 fill within culvert

Routine Inspection

2

3

Sketch
(Select Signature)

CK-2489

BENCH 7.2km

2014 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Inlet



inside culvert

CK-2489

BENCH 7.2km

2014 Inspection



Outlet