

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°20'12.4"	-122°8'13"
Crossing Name	South Statlu Creek
FSR #	8241
Branch #	3
Road Name	CHEHALIS-SOUTHSTATLU
User km	5.9
Current Load Rating (tonnes)	0
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	14.6
Deck Width (m)	5.8

Updated Data

Latitude	Longitude
°0'0"	-122°8'13"
HD Diff. (m)	5492145.0
Accuracy (m)	

Deactivated

Inspection

Date of Inspection

Inspector Name

Inspection Company

Inspector Comments

P.Eng Comments

Structure deactivated, no further inspections required.



P.Eng Seal

Dec 3/2015

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection

CBR iPad Offline Ver 0.21



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)

High Water ☐Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m)

Ice ☐

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)

CK-2038

CHEHALIS-SOUTHSTATLU 5.9km

2015 Inspection



deactivated



deactivated