

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°18'55.69"	-122°20'2.7"
Crossing Name	Not Known
FSR #	8648
Branch #	1
Road Name	FLORENCE LAKE
User km	13.11
Current Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	18.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°18'56.5"	-122°20'3.65"
HD Diff. (m)	31.4
Accuracy (m)	5

Inspection

Date of Inspection 2015-10-13 12:42:52 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Present load rating of L75 or 68 tonnes to continue.



P.Eng Seal

Dec 3/2015

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good

Piles or Posts Good

Ballast Wall Fair

Wing Wall N/A

Bracing Fair

Hardware Good

Fill Fair

Riprap Good

Bearings Good

Corrosion Protection Fair

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good 4 bays - bolted

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	03	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Left Bank Abutment when facing downstream

CK-2096

FLORENCE LAKE 13.11km

2015 Inspection



Right Bank Abutment when facing downstream



superstructure