

CK-2103

GARNET CREEK 8.8km

2015 Inspection



CBR iPad Offline Ver 0.20

CBR Data

Latitude	Longitude
49°24'57.3"	-121°35'23.7"
Crossing Name	East Fork Garnet Creek
FSR #	7558
Branch #	1
Road Name	GARNET CREEK
User km	8.8
Current Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
49°24'57.45"	-121°35'23.7"
HD Diff. (m)	7.3
Accuracy (m)	5

Inspection

Date of Inspection 2015-06-22 1:30:33 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Present load rating of L75 or 68 tonnes to continue.



P.Eng Seal

Dec 3/2015

CK-2103

GARNET CREEK 8.8km

2015 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y minor

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs Good geogrid

Bin Wall N/A

Concrete Good lock blocks

Caps or Sills Good treated timber sills

Piles or Posts N/A

Ballast Wall Good treated timbers

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

CK-2103

GARNET CREEK 8.8km

2015 Inspection

CBR iPad Offline Ver 0.20

**Deck**

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	Good	anti skid wearing
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Good	
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2103

GARNET CREEK 8.8km

2015 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2103

GARNET CREEK 8.8km

2015 Inspection



CBR iPad Offline Ver 0.20

Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	5.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2103

GARNET CREEK 8.8km

2015 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Right Bank Abutment when facing downstream

CK-2103

GARNET CREEK 8.8km

2015 Inspection



Left Bank Abutment when facing downstream



Structure ID