

CK-2107

HARRISON EAST 24.8km

2015 Inspection



CBR iPad Offline Ver 0.21

## CBR Data

|                              |                            |
|------------------------------|----------------------------|
| Latitude                     | Longitude                  |
| 49°32'11.4"                  | -121°45'41.8"              |
| Crossing Name                | Cogburn Creek              |
| FSR #                        | 5748                       |
| Branch #                     | 1                          |
| Road Name                    | HARRISON EAST              |
| User km                      | 24.8                       |
| Current Load Rating (tonnes) | 136                        |
| Structure Class              | Permanent Bridge           |
| Portable                     | N                          |
| Superstructure               | Steel I-beam               |
| Deck Type                    | Concrete Composite         |
| Abutment Left                | Steel Pipe and Precast Pad |
| Abutment Right               | Steel Pipe and Precast Pad |
| Spans                        | 2                          |
| Total Length (m)             | 43.6                       |
| Deck Width (m)               | 4.9                        |

## Updated Data

|              |               |
|--------------|---------------|
| Latitude     | Longitude     |
| 49°32'10.93" | -121°45'42.4" |
| HD Diff. (m) | 18.8          |
| Accuracy (m) | 5             |
| 24.1         |               |

## Inspection

Date of Inspection 2015-10-21 1:21:40 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace guardrail, risers and blocks; and brush approaches. Present load rating of L150 or 136 tonnes to continue.



P.Eng Seal

Dec 4/2015

CK-2107

HARRISON EAST 24.8km

2015 Inspection



CBR iPad Offline Ver 0.21

## Approach

Alignment Fair

Bridge Ahead Signs  
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y minor

Delineator Missing  
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing  
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 136090

Road Surface Good

## Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good steel plates

Piles or Posts Fair

Ballast Wall Fair treated timbers

Wing Wall N/A

Bracing Fair

Hardware Poor loose rail bolts

Fill Fair

Riprap Good

Bearings Good

Corrosion Protection Fair

CK-2107

HARRISON EAST 24.8km

2015 Inspection

CBR iPad Offline Ver 0.21

**Deck**

|                        |      |                                 |
|------------------------|------|---------------------------------|
| Running Surface        | Fair |                                 |
| Running Planks         | N/A  |                                 |
| Sub Deck               | N/A  |                                 |
| Ties                   | N/A  |                                 |
| Nails                  | N/A  |                                 |
| Deck to Girder Bolts   | N/A  |                                 |
| Concrete Deck          | Fair |                                 |
| Grout Pockets          | Fair |                                 |
| Deck Joints            | Good |                                 |
| Steel Deck Plate       | N/A  |                                 |
| Gravel Surface         | N/A  |                                 |
| Curb Rail/Blocks/Posts | Poor | rotten risers and blocks        |
| Hand Rails/Walkouts    | N/A  |                                 |
| Hardware               | N/A  |                                 |
| Overall Deck Condition | Poor | due to rotten risers and blocks |
| Gravel Depth (mm)      |      |                                 |

CK-2107

HARRISON EAST 24.8km

2015 Inspection



CBR iPad Offline Ver 0.21

**Steel/Concrete**

Serial/ID Plate

Girders Fair

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware N/A

Welded/grouted  
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/  
Shimming

| Needle Beam to Crib (m) |         |        | Needle Diameter (mm) |                   |           |         |
|-------------------------|---------|--------|----------------------|-------------------|-----------|---------|
| Stringer<br>Number      | Species | Peeled | Diameter<br>(mm)     | Rot Depth<br>(mm) | Condition | Comment |

CK-2107

HARRISON EAST 24.8km

2015 Inspection

CBR iPad Offline Ver 0.21



## Hazards

|                                          |      |             |                          |        |                          |
|------------------------------------------|------|-------------|--------------------------|--------|--------------------------|
| Estimated Present Water Level Depth (m)  | 1.0  | High Water  | <input type="checkbox"/> | Debris | <input type="checkbox"/> |
| Estimated Present Water Level Width (m)  | 20.0 | Aggradation | <input type="checkbox"/> | Scour  | <input type="checkbox"/> |
| Estimated High Water Level Clearance (m) | 3.0  | Ice         | <input type="checkbox"/> |        |                          |

Comments

## Repairs and Monitoring

| Repair Item | Priority | Repair Description |
|-------------|----------|--------------------|
|-------------|----------|--------------------|

|   |        |                          |
|---|--------|--------------------------|
| 1 | Medium | brush approaches         |
| 2 | Medium | replace guardrail system |

3

| Item | Monitor Description | Frequency |
|------|---------------------|-----------|
|------|---------------------|-----------|

1

2

3

Sketch  
(Select Signature)

**CK-2107**

**HARRISON EAST 24.8km**

**2015 Inspection**



Approach from Right Bank when facing downstream



compression seal missing



damaged riser



Approach from Left Bank when facing downstream

**CK-2107**

**HARRISON EAST 24.8km**

**2015 Inspection**



bullet holes through web of upstream girder



Right Bank Abutment when facing downstream



pier



Left Bank Abutment when facing downstream

**CK-2107**

**HARRISON EAST 24.8km**

**2015 Inspection**



damage to upstream pier pipe column