

CK-2115

HARRISON EAST 59.7km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°47'6.79"	-121°51'47.6"
Crossing Name	Big Silver Creek
FSR #	5748 Branch # 1
Road Name	HARRISON EAST
User km	59.7
Current Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	27.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°47'5.81"	-121°51'48.65"
HD Diff. (m)	37.1 Accuracy (m) 5

Inspection

Date of Inspection 2015-10-21 9:06:45 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Post bridge ahead signs. Present load rating of L150 or 136 tonnes to continue.



Dec 4/2015

CK-2115

HARRISON EAST 59.7km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good steel plates and rubber pads

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2115

HARRISON EAST 59.7km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Good

Gravel Depth (mm)

CK-2115

HARRISON EAST 59.7km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

6 bays - bolted

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2115

HARRISON EAST 59.7km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	post bridge ahead signs when active

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

CK-2115

HARRISON EAST 59.7km

2015 Inspection




Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Structure ID

CK-2115

HARRISON EAST 59.7km

2015 Inspection



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



splice plates



superstructure