

CK-2136

STS'AILES 31.1km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°31'6.99"	-121°54'1.2"
Crossing Name	Mystery Creek
FSR #	6314
Branch #	1
Road Name	STS'AILES
User km	31.1
Current Load Rating (tonnes)	63
Structure Class	Permanent Bridge
Portable	Y
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	27.5
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°31'6.87"	-121°54'7.38"
HD Diff. (m)	124.2
Accuracy (m)	5
30.0	

Inspection

Date of Inspection 2015-07-28 10:35:05 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Repair damage to deck panels. Brush approaches. Present load rating of CL-625 or 63 tonnes to continue. Update load rating sign.



05/01/2016

P.Eng Seal

CK-2136

STS'AILES 31.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 68040

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall Good

Concrete Good lock block bin wall on right bank

Caps or Sills Fair

Piles or Posts Fair

Ballast Wall Fair damage on running path

Wing Wall Good for bin wall

Bracing Good

Hardware Fair

Fill Good

Riprap Good

Bearings Fair

Corrosion Protection Good

CK-2136

STS'AILES 31.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair track damage and rebar exposed at approaches

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2136

STS'AILES 31.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good 5 bays, bolted

Bracing Good bolted

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2136

STS'AILES 31.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	10.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	brush approaches
2	Medium	repair exposed rebar on running path of deck panels
3		

Item	Monitor Description	Frequency
1	bearings	Routine Inspection
2		
3		

Sketch
(Select Signature)

CK-2136

STS'AILES 31.1km

2015 Inspection



Approach from Left Bank when facing downstream



deck



Deck



Deck

CK-2136

STS'AILES 31.1km


2015 Inspection



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Structure ID



panel 1 damage underneath

CK-2136

STS'AILES 31.1km

2015 Inspection



panel 1 damage



bearing plates and pads - typical



Right Bank Abutment when facing downstream



superstructure