

CK-2264

STAVE RIVER 13km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°30'13.39"	-122°15'51.4"
Crossing Name	Side Creek
FSR #	8013 Branch # 1
Road Name	STAVE RIVER
User km	13
Current Load Rating (tonnes)	30
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	7.5
Deck Width (m)	5

Updated Data

Latitude	Longitude
49°30'13.26"	-122°15'50.83"
HD Diff. (m)	12.3 Accuracy (m) 5

Inspection

Date of Inspection 2015-09-22 1:49:06 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

This structure has 2 layers of log stringers and only the bottom layer can properly assessed. The top layer were added in 2012 as a temporary measure in order to facilitate works at the time. The entire structure (crib logs, tiebacks and stringers) has further deteriorated since then. Because the top layer of stringers have not been properly inspected the structure remains down-rated. Present load rating of 30 tonnes to continue. Post load rating sign.



07/01/2016

P.Eng Seal

CK-2264

STAVE RIVER 13km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor none

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs Fair 3x

Tie Backs Fair 4x

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Poor none

Bearings Fair

Corrosion Protection N/A

CK-2264

STAVE RIVER 13km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface	N/A	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Fair	
Curb Rail/Blocks/Posts	Fair	
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Fair	
Gravel Depth (mm)	200	

CK-2264

STAVE RIVER 13km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware N/A NA

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Cw	Y	660	50	Fair		sap and pocket rot
2	Cw	Y	600	30	Fair		sap rot
3	Cw	Y	700	40	Fair		sap rot
4	Cw	Y	590	30	Fair		sap rot
5	Cw	Y	560	30	Fair		sap rot
6	Cw	Y	550	40	Fair		sap rot
7	Cw	Y	570	120	Poor		sap and heart rot

CK-2264

STAVE RIVER 13km

2015 Inspection



CBR iPad Offline Ver 0.21

Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments there are 2 layers of stringers in the bridge

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	remove gravel deck to properly assess the top row of stringers

2	High	post load rating sign
---	------	-----------------------

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)

CK-2264

STAVE RIVER 13km

2015 Inspection



Approach from Left Bank when facing downstream



top log stringer exposed



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream

CK-2264

STAVE RIVER 13km

2015 Inspection



Left Bank Abutment when facing downstream



Stringers