

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



CBR iPad Offline Ver 0.20

CBR Data

Latitude	Longitude
49°19'35.1"	-121°20'56"
Crossing Name	Berkey Creek
FSR #	8113
Branch #	2
Road Name	WRAY-BERKEY CREEK
User km	4.2
Current Load Rating (tonnes)	0
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	8.5
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°19'33.72"	-121°20'56"
HD Diff. (m)	43.3
Accuracy (m)	5

Inspection

Date of Inspection 2015-06-23 12:05:20 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Structure condemned, 0 tonnes load rating. Replace entire structure prior to any works.



06/01/2016

P.Eng Seal

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

 Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor none

Posted Load Rating not posted but road extremely grown over - no vehicle access

Road Surface Poor grown over

Abutment

Log/Timber Cribs Fair

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall Poor rotten on left bank, non existent on right bank

Wing Wall N/A

Bracing N/A

Hardware Poor loose

Fill Fair

Riprap Poor none

Bearings Fair

Corrosion Protection N/A

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Deck

Running Surface	N/A	grown over
Running Planks	Poor	rotten
Sub Deck	N/A	
Ties	Poor	rotten
Nails	Poor	protruding
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	rotten
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Poor	replace entire structure prior to use
Gravel Depth (mm)		

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

NA

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection

CBR iPad Offline Ver 0.20



Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments structure is rotten and requires complete replacement prior to activity

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Left Bank Abutment when facing downstream

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



data logger



deck from below



Right Bank Abutment when facing downstream



Stringers

CK-2315

WRAY-BERKEY CREEK 4.2km

2015 Inspection



Stringers