

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°17'38"	-122°5'1.8"
Crossing Name	East Fork
FSR #	10326
Branch #	1
Road Name	NORRISH CREEK
User km	16.1
Current Load Rating (tonnes)	91
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	30.5
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
49°17'37.77"	-122°5'1.5"
HD Diff. (m)	9.4
Accuracy (m)	5
16.0	

Inspection

Date of Inspection 2015-07-29 10:44:19 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Present load rating of L100 or 91 tonnes to continue.



05/01/2015

P.Eng Seal

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 90680

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2445

NORRISH CREEK 16.1km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	10.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Left Bank Abutment when facing downstream

CK-2445

NORRISH CREEK 16.1km

2015 Inspection



Right Bank Abutment when facing downstream



superstructure



Structure ID