

CK-2457

NORRISH CREEK 13.6km

2015 Inspection

CBR iPad Offline Ver 0.21



CBR Data

Latitude	Longitude		
49°16'31.29"	-122°5'22.8"		
Crossing Name	Unknown		
FSR #	10326	Branch #	1
Road Name	NORRISH CREEK		
User km	13.6		
Current Load Rating (tonnes)	63		
Structure Class	Major Culvert		
Culvert Type	Open Bottom		
Culvert Material	Corrugated Steel		
Opening Height (mm)	1440		
Opening Width (mm)	2740		
Inlet Cover (mm)	700		
Outlet Cover (mm)	700		
Culvert Gradient %			
Culvert Length (m)	10		

Updated Data

Latitude	Longitude		
49°16'31.66"	-122°5'23.75"		
HD Diff. (m)	22.1	Accuracy (m)	5
600			

Inspection

Date of Inspection 2015-07-29 10:26:47 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Streambed material eroding approximately 3 meters from the outlet of the culvert - requires monitoring. Material under some portions of the concrete footings still eroding - requires monitoring. The structure should be continually inspected especially during/after periods of heavy rainfall. If the streambed material continues to erode and undermine the footings additional repair work will be required. The site may require a different structure installed. Present load rating of BCL-625 or 63 tonnes to continue.



06/01/2016

P.Eng Seal

CK-2457

NORRISH CREEK 13.6km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated NA

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Fair

Riprap Fair

Bearings

Corrosion Protection

CK-2457

NORRISH CREEK 13.6km

2015 Inspection

CBR iPad Offline Ver 0.21



Culvert

Baffles	N/A	
Bolted Connections	Good	
Coating	Good	
Coupled Connections	N/A	
Embedment Materials	Fair	
Fill	Fair	
Floor	Unrated	NA
Footing	Fair	concrete footing exposed and slightly scoured in localized areas
Head Walls	N/A	
Inlet	Fair	steep stream coming into culvert
Outlet	Fair	steep drop 3 meters from outlet
Overall	Fair	
Rip Rap	Fair	
Roof	Good	
Sidewalls	Good	
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

CK-2457

NORRISH CREEK 13.6km

2015 Inspection

CBR iPad Offline Ver 0.21



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Species	Peeled	Needle Beam to Crib (m) Diameter (mm)	Needle Diameter (mm) Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	---	---	-----------	---------

CK-2457

NORRISH CREEK 13.6km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1 footing scour

Anually

2

3

Sketch
(Select Signature)

CK-2457

NORRISH CREEK 13.6km

2015 Inspection



Approach from Right Bank when facing downstream



Inlet



Approach from Left Bank when facing downstream



looking through culvert from inlet

CK-2457

NORRISH CREEK 13.6km

2015 Inspection



upstream from inlet



Structure ID



Outlet