

CK-2473

NAHATLATCH 45km

2015 Inspection



CBR iPad Offline Ver 0.20

CBR Data

Latitude	Longitude
49°54'49.5"	-121°59'12.4"
Crossing Name	Whistle Pig Creek
FSR #	6996
Branch #	1
Road Name	NAHATLATCH
User km	45
Current Load Rating (tonnes)	10
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	13
Deck Width (m)	5

Updated Data

Latitude	Longitude
49°54'48.42"	-121°59'12.4"
HD Diff. (m)	38.9
Accuracy (m)	10
	45.3
	13.0

Inspection

Date of Inspection 2015-07-22 11:13:33 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

5 tonnes load rating. Monitor holes in deck.

Handwritten signature and date:
T.W. Miller
July 23 2015



P.Eng Seal

CK-2473

NAHATLATCH 45km

2015 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Fair

 Bridge Ahead Signs
Missing ☐ 0 ☒ 1 ☐ 2

Brushing Required Y

 Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

 Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor none

Posted Load Rating 5

Road Surface Poor requires surfacing in many locations

Abutment

Log/Timber Cribs Fair

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A none

Wing Wall N/A

Bracing N/A

Hardware Poor loose

Fill Fair

Riprap Poor none

Bearings Fair

Corrosion Protection N/A

CK-2473

NAHATLATCH 45km

2015 Inspection

CBR iPad Offline Ver 0.20

**Deck**

Running Surface	N/A	requires surfacing in many locations
Running Planks	Poor	rotting
Sub Deck	N/A	
Ties	Poor	rotting
Nails	Poor	protruding
Deck to Girder Bolts	Poor	loose
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Poor	rotting
Gravel Depth (mm)		

CK-2473

NAHATLATCH 45km

2015 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware na

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Fd	Y	800	210	Poor		sap and pocket rot
2	Fd	Y	810	110	Poor		sap and pocket rot
3	Fd	Y	700	90	Poor		sap and pocket rot
4	Fd	Y	890	230	Poor		sap and heart rot
5	Fd	Y	800	130	Poor		sap and pocket rot

CK-2473

NAHATLATCH 45km

2015 Inspection



CBR iPad Offline Ver 0.20

Hazards

Estimated Present Water Level Depth (m)	0.8	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2473

NAHATLATCH 45km

2015 Inspection



Approach from Right Bank when facing downstream



deck



load rating sign



hole in deck

CK-2473

NAHATLATCH 45km

2015 Inspection



tie condition



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream

CK-2473

NAHATLATCH 45km

2015 Inspection



Stringers



stringer 1 - conks starting to form