

CK-2507

Winslow Creek 5.0km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
°0'0"	°0'0"
Crossing Name	unknown
FSR #	Branch #
Road Name	Winslow Creek
User km	5.0
Current Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Sill -Temporary Materials
Abutment Right	Sill -Temporary Materials
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°30'45.42"	-122°11'16.3"
HD Diff. (m)	9998670.9
Accuracy (m)	5

Inspection

Date of Inspection 2015-09-22 4:16:51 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace delineators and post bridge ahead signs. Present load rating of L75 or 68 tonnes to continue.



06/01/2016

P.Eng Seal

CK-2507

Winslow Creek 5.0km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good log sills

Piles or Posts N/A

Ballast Wall Good logs

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

CK-2507

Winslow Creek 5.0km

2015 Inspection

CBR iPad Offline Ver 0.21

**Deck**

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate Good

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Good

Gravel Depth (mm)

CK-2507

Winslow Creek 5.0km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Unrated can't see

Bracing Unrated can't see

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2507

Winslow Creek 5.0km

2015 Inspection



CBR iPad Offline Ver 0.21

Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	post delineators and bridge ahead signs

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

CK-2507

Winslow Creek 5.0km

2015 Inspection



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Approach from Right Bank when facing downstream



superstructure

CK-2507

Winslow Creek 5.0km

2015 Inspection



Structure ID



Right Bank Abutment when facing downstream



Deck