

CK-2131

STS'AILES 16.4km

2016 Inspection



CBR iPad Offline Ver 0.23

CBR Data

Latitude	Longitude
49°26'3.9"	-121°50'50.2"
Crossing Name	Not Known
FSR #	6314
Branch #	1
Road Name	STS'AILES
User km	16.4
Current Load Rating (tonnes)	136
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	1800
Opening Width (mm)	1800
Inlet Cover (mm)	1000
Outlet Cover (mm)	1200
Culvert Gradient %	3
Culvert Length (m)	15.5

Updated Data

Latitude	Longitude
49°26'4.35"	-121°50'50.68"
HD Diff. (m)	17.0
Accuracy (m)	5
15.8	

Inspection

Date of Inspection 2016-07-21 9:02:15 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

not a major culvert

P.Eng Comments

Culvert is only 1800mm diameter, inspect with regular road inspections. Present load rating of L150 or 136 tonnes can continue. Monitor outlet scour.



01/03/2017

P.Eng Seal

CK-2131

STS'AILES 16.4km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated NA

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Fair

Riprap Fair

Bearings

Corrosion Protection

CK-2131

STS'AILES 16.4km

2016 Inspection

CBR iPad Offline Ver 0.23

**Culvert**

Baffles	N/A	
Bolted Connections	Fair	
Coating	Fair	
Coupled Connections	N/A	
Embedment Materials	N/A	
Fill	Fair	
Floor	Fair	
Footing	NA	
Head Walls	N/A	
Inlet	Fair	
Outlet	Fair	2.0m drop
Overall	Fair	
Rip Rap	Fair	
Roof	Fair	
Sidewalls	Fair	
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

CK-2131

STS'AILES 16.4km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.8	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



weir located 25 meters upstream from culvert



multiplate



Inlet



outlet from inside culvert



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream