

CK-2145

STS'AILES 61.2km

2016 Inspection

CBR iPad Offline Ver 0.23



CBR Data

Latitude	Longitude		
49°41'29.19"	-122°3'41.9"		
Crossing Name	Not Known		
FSR #	6314	Branch #	1
Road Name	STS'AILES		
User km	61.2		
Current Load Rating (tonnes)			
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	4.6		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
49°41'28.82"	-122°3'41.9"		
HD Diff. (m)	11.8	Accuracy (m)	5
60.0			
Culverts	NA		
NA	NA		
Gravel	NA		
NA	2 - 750mm diameter culverts		

Inspection

Date of Inspection 2016-07-28 11:38:07 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

structure is 2 x 750mm steel pipes
inspect with road inspections

P.Eng Comments

Clean inlet and monitor aggradation. Remove site from inventory and inspect with regular road inspections.



01/03/2017

P.Eng Seal

CK-2145

STS'AILES 61.2km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Fair

VC and HC right bank approach

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Poor 4x4 access only from Harrison

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill N/A

Riprap N/A

Bearings N/A

Corrosion Protection N/A

CK-2145

STS'AILES 61.2km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface	Fair	4x4 access only from Harrison
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	N/A	
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2145

STS'AILES 61.2km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0.3	Ice	☐		
Comments	structure is 2 x 750mm steel pipes				

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Clean inlet

2

3

Item	Monitor Description	Frequency
1	aggradation at inlet	Routine inspection

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Inlet