

CK-2149

WALIAN CREEK 7.2km

2016 Inspection



CBR iPad Offline Ver 0.23

CBR Data

Latitude	Longitude
49°27'11.99"	-121°54'39.4"
Crossing Name	Walain Creek
FSR #	6314
Branch #	8
Road Name	WALIAN CREEK
User km	7.2
Current Load Rating (tonnes)	0
Structure Class	Temporary Bridge
Portable	N
Superstructure	Timber - untreated stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	10
Deck Width (m)	2

Updated Data

Latitude	Longitude
49°27'11.07"	-121°54'39.06"
HD Diff. (m)	29.5
Accuracy (m)	5
0 tonnes	
Y	
Timber - untreated stringers	
Timber - Treated	
Concrete Lock Blocks	
Concrete Lock Blocks	
1	
15.1	
1.65	

Inspection

Date of Inspection 2016-07-22 1:38:10 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

stringers have numerous small conks and will not last long
bearing on right bank is partially on blocks -10.6m span, otherwise 14.5m span

P.Eng Comments

Bridge condemned, 0 tonnes load rating. Remove structure and block access ASAP.



CK-2149

WALIAN CREEK 7.2km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Fair lock blocks

Caps or Sills Fair treated 100mm x 150mm

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection N/A

CK-2149

WALIAN CREEK 7.2km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	Fair	100mm x 150mm at 190mm centers - treated
Nails	Fair	
Deck to Girder Bolts	Fair	every tie is nailed to log stringer
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	100mm x150mm stacked 2 high - treated
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2149

WALIAN CREEK 7.2km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
1	Fd	Y	520	20	Fair	small conk starting to show
2	Fd	Y	520	50	Fair	lots of small conks present with localized rot

CK-2149

WALIAN CREEK 7.2km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Remove structure and block access to site

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



ATV bridge



Approach from Right Bank when facing downstream



guardrail



Approach from Left Bank when facing downstream



Stringers



Right Bank Abutment when facing downstream



left bank sill



partial bearing on right bank