

CK-2163

LOST CREEK 1.1km

2016 Inspection

CBR iPad Offline Ver 0.23



CBR Data

Latitude	Longitude
49°17'16.9"	-122°13'43.2"
Crossing Name	Not Known
FSR #	8466
Branch #	1
Road Name	LOST CREEK
User km	1.1
Current Load Rating (tonnes)	91
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	13
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°17'16.91"	-122°13'43.94"
HD Diff. (m)	14.8
Accuracy (m)	10

Inspection

Date of Inspection 2016-08-11 1:44:49 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Present load rating of L100 or 91 tonnes to continue.



15/02/2017

P.Eng Seal

CK-2163

LOST CREEK 1.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 91000

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good integrated cap/wall

Piles or Posts Unrated buried

Ballast Wall Good

Wing Wall N/A

Bracing Unrated buried

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Unrated buried towers

CK-2163

LOST CREEK 1.1km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Good

Gravel Depth (mm)

CK-2163

LOST CREEK 1.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Good 6 slabs with welded keys

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted shear connectors Good

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2163

LOST CREEK 1.1km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



looking upstream from deck



Deck



looking downstream from deck



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Upstream Profile