

CK-2167

LOST CREEK 8km

2016 Inspection



CBR iPad Offline Ver 0.23

CBR Data

Latitude	Longitude
49°20'26.4"	-122°14'32.6"
Crossing Name	Lost Creek
FSR #	8466
Branch #	1
Road Name	LOST CREEK
User km	8
Current Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	24.4
Deck Width (m)	4.95

Updated Data

Latitude	Longitude
49°20'25.48"	-122°14'32.09"
HD Diff. (m)	30.4
Accuracy (m)	5

Inspection

Date of Inspection 2016-08-11 2:44:21 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Repair scour under left upstream lock blocks ASAP and place riprap in front to protect. The riprap on the right upstream abutment is also starting to scour, repair that at same time. The present load rating of L75 or 68 tonnes can continue for now. Inspect again prior to heavy rains.



P.Eng Seal

Sept 13/2016

CK-2167

LOST CREEK 8km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs Good geotextile between each row of blocks

Bin Wall N/A

Concrete Fair scour under upstream left bank

Caps or Sills Good treated timbers

Piles or Posts N/A

Ballast Wall Good

Wing Wall Fair scour noted under upstream left bank

Bracing N/A

Hardware N/A

Fill Fair

Riprap Fair upstream corners starting to scour

Bearings Good

Corrosion Protection N/A

CK-2167

LOST CREEK 8km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate Fair

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2167

LOST CREEK 8km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Good ASP

Diaphragms Unrated inside box beam

Bracing Unrated inside box beam

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2167

LOST CREEK 8km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	12.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	repair scour under left bank blocks ASAP
2	High	repair scoured riprap at both upstream abutments
3		

Item	Monitor Description	Frequency
1	scour	Anually
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



looking upstream from deck



Deck



looking downstream from deck



Approach from Left Bank when facing downstream



upstream left bank lock block (abutment scour)



Right Bank Abutment when facing downstream



Upstream Profile



upstream left bank riprap scour - lock block scour



Left Bank Abutment when facing downstream



upstream right bank riprap scour



Structure ID