

CK-2170

LOST CREEK 17.1km

2016 Inspection

CBR iPad Offline Ver 0.23



CBR Data

Latitude	Longitude		
49°23'48.3"	-122°13'48.4"		
Crossing Name	Teripocki Creek		
FSR #	8466	Branch #	1
Road Name	LOST CREEK		
User km	17.1		
Current Load Rating (tonnes)	54		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Compo Girders		
Deck Type	Concrete		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	24.4		
Deck Width (m)	4.3		

Updated Data

Latitude	Longitude		
49°23'47.61"	-122°13'47.04"		
HD Diff. (m)	34.8	Accuracy (m)	5

Inspection

Date of Inspection 2016-08-31 11:29:05 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Post bridge ahead signs. Present load rating of L60 or 54 tonnes to continue.



16/02/2017

P.Eng Seal

CK-2170

LOST CREEK 17.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Good BR

Bearings Good

Corrosion Protection Good

CK-2170

LOST CREEK 17.1km

2016 Inspection

CBR iPad Offline Ver 0.23



Deck

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Good

Gravel Depth (mm)

CK-2170

LOST CREEK 17.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2170

LOST CREEK 17.1km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	post bridge ahead signs

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



looking upstream



Deck



looking downstream



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



superstructure