

CK-2219

PITT RIVER 9.8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

CBR Data

Latitude	Longitude
49°37'10.59"	-122°38'40.5"
Crossing Name	Corbold Creek
FSR #	8394
Branch #	1
Road Name	PITT RIVER
User km	9.8
Current Load Rating (tonnes)	109
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	39.6
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°37'9.84"	-122°38'41.41"
HD Diff. (m)	29.8
Accuracy (m)	5

Inspection

Date of Inspection 2016-08-04 5:16:36 PM

Inspector Name Jamie Rupar Gilliatt

Inspection Company SNT Engineering

Inspector Comments

The bridge is generally in good condition with a few routine maintenance items required.

P.Eng Comments

Replace sealant at left abutment panel joint and seal all grouted panel joints. Brush approaches and clean debris from deck. Present load rating of L120 or 109 tonnes to continue.



24/02/2017

P.Eng Seal

CK-2219

PITT RIVER 9.8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Approach

Alignment Fair Horizontal and vertical curve.

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y Minor brushing.

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Old guide logs starting to rot.

Posted Load Rating No load posting sign.

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts Good Steel pipes.

Ballast Wall Good Precast concrete ballast wall.

Wing Wall N/A

Bracing Good Mostly buried in fill.

Hardware Fair

Fill Good

Riprap Good

Bearings Fair All bearings are bulging.

Corrosion Protection Fair Painted substructure.

CK-2219

PITT RIVER 9.8km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT



Deck

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Fair	Wear in wheel tracks.
Grout Pockets	Fair	Typically below level of deck due to wear.
Deck Joints	Fair	Section of failed joint in wheel tracks at left abutment. Corrosion noted on girder at some panel joint locations.
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Good	Replaced since last inspection.
Hand Rails/Walkouts	N/A	
Hardware	Good	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2219

PITT RIVER 9.8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Steel/Concrete

Serial/ID Plate

Girders Good

Corrosion of top flange and web at a few panel joint locations. Measurable section loss not anticipated based on extent of corrosion.

Diaphragms Good

8 diaphragms.

Bracing Good

Plan bracing in end bays.

Under Trussing N/A

Hardware Good

Bolted connections for diaphragms, bracing and splice.

Welded/grouted shear connectors N/A

Log

Log Curbs N/A

Needle Beam N/A

Needle Lashing/Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2219

PITT RIVER 9.8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Hazards

Estimated Present Water Level Depth (m)	0.75	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	25	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3	Ice	☐		

Comments Spawning channel.

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Low	Clear debris from deck. Brush approaches. Replace sealant at left abutment panel joint. Seal all grouted panel joints.

2

3

Item	Monitor Description	Frequency
1	Monitor wear of grout pockets.	Routine Inspection

2	Monitor bulging of bearings.	Routine Inspection
---	------------------------------	--------------------

3

Sketch
(Select Signature)



Left Approach Facing Bridge



Deck



Left Approach Facing Away From Bridge



Guardrail



Typical Grout Pocket Condition



Looking Downstream



Looking Upstream



Right Approach Facing Away From Bridge



Right Approach Facing Bridge



Downstream Elevation



Failed Deck Panel Sealant at Left Abutment



Upstream Elevation



Right Bank Abutment



Left Bank Abutment



Girders



Typical Bulging Bearings



Right Bank Abutment



Corrosion of Girder at Panel Joint



Left Bank Abutment